

## Facility information

Facility name: Greenbush School ISD #2683Date: September 10, 2021Leak number: LS0021571Incident  
number: 199749

The Minnesota Pollution Control Agency (MPCA) has determined the following emergency conditions exist at the above-referenced site: Fuel oil tank discovered empty, 1,000 gallons missing. Fuel smell in classroom adjacent to the tank.

## Emergency actions

The following actions should be taken within 48 hours to remediate the emergency conditions:

- ☐ Recovery and control of pooled petroleum on land
- ☐ Recovery and control of petroleum on surface or groundwaters of the state
- ☐ Recovery and control of petroleum infiltrating a sanitary or storm sewer
- ☒ Recovery and control of petroleum infiltrating a building or structure
- ☒ Removal and control of petroleum vapors in a building, structure or sewer
- ☐ Relocation of affected residents
- ☒ Excavation of petroleum contaminated soil to eliminate emergency conditions
- ☐ Product removal from a tank
- ☐ Soil borings/monitoring well installation to assess the emergency conditions
- ☒ Collecting and analyzing surface water, groundwater, soil, or air samples to assess or monitor the emergency situation
- ☐ Providing an alternate water supply to an affected well owner
- ☒ Report of emergency actions taken, findings, and recommendations for additional work
- ☐ Other, specify: [manually enter text]

## Corrective actions

If you plan to seek Petrofund reimbursement for any eligible corrective action costs, in accordance with Minn. R. 2890.0089, the MPCA may assist in documenting that the emergency conditions at this site posed a threat to the public health and welfare or the environment and that there was not sufficient time to obtain bids or proposals for the services requested above. Reimbursement determinations are made by the Petrofund Board.