# **Lakeland Joint School District #272**

5506 N. Washington St. Rathdrum, ID 83858 208-687-0431

LJSD Vision: A community committed to academic excellence ... dedicated to student success.



# Board Agenda Item Request

AGENDA ITEM: Budget Reallocation for Plant Facility Levy Funds

PURPOSE: Budget Reallocation for Plant Facility Levy Funds

MEETING DATE: October 9, 2024

PREPARED BY: Jessica Grantham, Adam Wilson

#### **INFORMATIONAL SUMMARY:**

The Facilities Department identified several classrooms/rooms within the 8th-grade hallway at Lakeland Middle School that will require asbestos abatement and flooring replacement. Due to the scope of the project, Christmas break does not provide enough time to complete the abatement work. We recommend that the work be completed as soon as school is out in June 2025.

We received three carpet tile replacement quotes, and are currently sourcing quotes for polished concrete. We are also seeking additional quotes on the abatement to comply with the Idaho Statutes and our Procurement Policy 7400. The project is estimated to cost \$210,000.

#### Carpet Tile Quotes:

Fairway Floor, Inc.	Accent Floor & Design	Comack's Flooring America				
Abatement Quote: (Need 3 per policy)						
Compass Construction						

Additionally, Lakeland High School's Tennis Courts are failing and have multiple dead spots throughout the playing surface. To make the surface playable for the Spring season, the existing failing patches need to be removed and repaired. This will be a temporary fix until we can replace the courts as recommended. (Replacement is estimated at \$625,000). The fix was quoted at \$74,620. The tennis courts will need to be repaired as soon as possible to ensure they are playable this Spring.

Plant Facility Levy Funds may only be used for Capital Projects or maintenance lasting greater than one year. These projects fall within the parameters of the levy requirements.

Page 1 of 24

#### FINANCIAL CONSIDERATIONS:

The Board approved the following budget for the 2025 Plant Facility Levy.

	Estimated			Remaining
Project	Amount	Encumbered	Expensed	Funds
FY24 - Building Budgets	\$98,070	\$2,836	\$56,123	\$39,111
FY24 - DO Security Upgrades	\$20,000			\$20,000
FY24 - Emergency Repairs Fund	\$100,000			\$100,000
FY24 - LMS Gym Floor	\$38,000	\$38,000		\$0
FY24 - LMS Gym Bleachers	\$105,000			\$105,000
FY24 - Concrete Projects	\$350,000			\$350,000
FY25 - Additional Concrete Projects	\$266,469			\$25,000
FY25 - Emergency Repairs Fund	\$100,000			\$100,000
FY25 - Building Budgets	\$100,000			\$100,000
FY25 - BKE/GE Playgrounds	\$120,000	\$47,152	\$70,728	\$2,120
FY25 - LHS Irrigation	\$20,000			\$20,000
FY25 - Parking Lot - AE	\$20,000			\$20,000
FY25 - Parking Lot - BKE	\$25,000			\$25,000
FY25 - Parking Lot - TLE	\$25,000			\$25,000
FY25 - Parking Lot - LHS	\$40,000			\$40,000
FY25 - Parking Lot - MVHS	\$15,000			\$15,000
FY25 - Parking Lot - LMS	\$25,000			\$25,000
FY25 - Safety Film on Windows	\$75,000			\$75,000
FY25 - Siding Project Change Order	\$107,000			\$107,000
FY25 - Siding Project - SLE Drip Edge	\$14,000		\$13,687	\$313
FY25 - Siding Project - Gutters SLE, AE	\$18,000		\$14,445	\$3,555
FY25 - BKE Carpet (whole building)	\$100,000			\$100,000
FY25 - AE, GE, LHS, SLE (continuation)	\$220,000			\$220,000
FY25 - VCT Tile - GE, BKE Cafeteria	\$40,000			\$40,000
Total Approved Budget	\$1,952,539	\$87,988	\$154,983	\$1,709,568

Our recommendation would be to utilize the funds set aside for the carpet continuation projects to complete the abatement and flooring at Lakeland Middle School (\$210,000). To complete the Lakeland High School Tennis Courts repair, we can utilize the remaining \$10,000 from the carpet continuation project, \$40,000 from the VCT tile project, with the remaining \$24,620 coming out of emergency repairs.

The forthcoming School Facilities Modernization Funds can be used to complete the carpet continuation and VCT tile projects that we are recommending to place on hold. As we are at the beginning of the school year, leaving funds available in the Emergency Repairs line items is imperative for future unknown issues.



(208)777-7711 Fax (208)777-7722 Location: Corner of Hwy. 41 & 16<sup>th</sup> Ave. Mailing Address: P.O. Box 3310 Post Falls, ID 83877 Date: 9-16-24

Attention: Christine

Reference:

**LJHS** 

D.... 1 D...

Carpet, Vinyl, Tile, Hardwood Flooring, Laminate Flooring and Countertops

If a specific service is not stated below it is not included!

Supply and install carpet tile and rubber base Includes adhesive and minor floor prep

Room #6 \$4427.00

Room #7 \$4427.00

Room #8 \$4427.00

Room #9 \$4828.00

Room #10 \$4427.00

Room #14 \$4099.00

Room #16 \$2021.00

Room #17 \$3402.00

Thank You, Ryan Wells Contract Specialist

Terms are 75% down and balance upon completion. Add 3% Surcharge for all Credit Card Purchases. All past due balances will incur interest at a rate of 1.5% per month or 18% per annum. Minimum Finance charge will be \$39.00. Company Policy requires us to lien property 45 days from installation date. Fairway Floor Inc. is not responsible for damage to our installed products, or to any surrounding products caused by moisture intrusion from substrate, from leaks, or from topically applied water. Fairway Floor does not reconnect any gas appliances or water lines. Any unforeseen floor prep will be pre-approved by customer and charged at an hourly rate. Special order materials cannot be returned or refunded. Signing is your agreement of these statements and all above terms. Please confirm the accuracy of the above work prior to signing.

Customer Signature:	Date:

9/20/2024 12:40:22 PM Page 1



Accent Floors & Design 6040 N Government Way #401 Coeur D Alene ID 83815 208-664-8830

Proposal #: 1555
SaleDate: 9/20/2024

Next Install:

Sales Rep: Stephen Boyd

SOLD TO:

LAKELAND SCHOOL DISTRICT 272
15506 WASHINGTON AVE
RATHDRUM ID 83858
208-687-0431 jessica.Grantham@lakeland272.org

#### SHIPPED TO

LAKELAND MIDDLE SCHOOL

MATERIALS			QUANTITY	PRICE	TOTAL
1 Bandwidth Carpet	Tile 6 S/y-54.00	Ancient Root-883-011	6,102.00 SqFt	\$2.99	\$18,244.98
CARP	ET TILE FOR CLASRO	OMS 6,7,8,9,10,14,16,17			
2 Wall Base Ts Rubb	or 4.5 Toe 4-31.25	Charcoal-400190001	1,080.00 LnFt	\$1.39	\$1,501.20
4" RUE	BBER BASE COLOR T	O BE SELECTED			
4 Finale Wall Base A	dhesive 30oz-1.00	White 2040-finale-030	16.00 Each	\$10.33	\$165.28
5 Versatile Carpet Til	e Adh 4gal-1.00	versatile-4	16.00 Each	\$194.46	\$3,111.36
LABOR			QUANTITY	PRICE	TOTAL
1 CARPET INSTALL	ATION		6,102.00 SqFt	\$1.00	\$6,102.00
2 COVE BASE			1,080.00 LnFt	\$1.00	\$1,080.00
3 FLOOR PREP			1.00 Each	\$1,000.00	\$1,000.00
MINIM	AL FLOOR PREP ETC				

Comments: THIS BID IS FOR CARPET ,RUBBER BASE , AND LABOR ONLY. THERE IS NO DEMO OR ABATEMENT FOR ASBESTOS IN THIS BID.FLOOR

PREP WILL BE ADDED TO BID AT TIME OF INSTALLATION

SubTotal: \$31,204.82 Misc Chg: \$0.00

Total: \$31,204.82
Payments: \$0.00
Balance: \$31,204.82

Accent Floors and Design would like to thank you for your business! We sincerely appreciate our clients! Continuing relationships and our client's peace of mind is our priority. We try to accomplish this through fair pricing, amazing customer service and strive to be an integral part of your project.

Material Only Orders require full payment at time of purchase.

Material and Installation orders require a 60% deposit. Balances are due at completion of job.

All pricing is based on cash or check payments. Credit cards add a 3% fee. Bank Transfers add a 1.2% fee.

#### PLEASE NOTE:

There are no returns on materials purchased. Accent Floors will not be held responsible for changes to a project that may result in product and or quantity changes after purchase. Client/Contractor assumes responsibility for any additional materials or labor required to complete the project. Material only orders require the client or contractor to be responsible for sq ft and quantity of materials requested. Overages can not be returned, and shortage is not the responsibility of Accent Floors and Design.

#### WAREHOUSE PICKUP REQUIREMENTS:

We offer warehouse pickups between 8am and 4pm Monday through Friday. Please give us 24 hours notice so we may be respectful of your time.

Thank you! Accent Floors and Design COMACK'S FLOORING AMERICA 8961 N COMMERCE DRIVE HAYDEN, ID 83835 208.772.9579 Proposal #: CO002153 Sale Date: 09/19/2024

Install Date:

Sales Rep: COMACK, G

Sales Rep:

**SOLD TO** 

LAKEland School District, 15506 Washington Ave. Rathdrum ID 83858 Adam 208-818-3747 SHIPPED TO

Printed 09/24/24 16:07:46

Lakeland Middle School

Various classrooms

15601 ID-41

Rathdrum ID 83858

MATERIALS		QUANTITY	PRICE	TOTAL
(1) Change In Attitude TI-48.00	TBD			\$22,101.44
(2) Dynamic Pre-sen Adhesive 4gal-1.00	Pressure Sensitive Dbs-dynamic			\$1,307.04
(3) Cove Base 080 Vinyl 4 Cb 120'-0.00	TBD			\$1,260.00

Materials Subtotal: \$24,668.48

LABOR	QUANTITY	PRICE	TOTAL
(1) Carpet-Glue Down,			\$6,430.74
(3) Rubber Base Install,			\$1,050.00

Labor SubTotal: \$7,480.74

Comments:

Subtotal:

\$32,149.22

Misc:

\$0.00

Total: Payments:

\$32,149.22 \$0.00

Balance:

\$32,149.22



**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Insured: Lakeland JR High\_ Classrooms

Property: 15506 Washington Ave

Rathdrum, ID 83858

Claim Rep.: Daniel Burns
Position: Estimator

Company: Greater Inland Property Solutions

Business: 4529 S Napa Street

Spokane, WA 99223

Estimator: Daniel Burns
Position: Estimator

Company: Greater Inland Property Solutions

Business: 4529 S Napa Street

Spokane, WA 99223

Contractor: Business: (509) 532-0055

Company: Compass Construction Inc Business: 2503 East Riverside Spokane, WA 99202

Claim Number: N/A Policy Number: N/A Type of Loss: Addition

Date Contacted: 9/5/2024 11:44 AM

Date of Loss: 9/5/2024 12:00 AM Date Received: 8/16/2024 12:00 AM Date Inspected: 9/5/2024 12:00 AM Date Entered: 9/5/2024 9:28 AM

Price List: IDCD8X\_MAR23

Restoration/Service/Remodel

Estimate: LAKELAND\_ASBESTOS

#### **ESTIMATE**



2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Thank you for choosing Compass Construction for your Damage Repair needs. Compass is a full-service restoration contractor specializing in residential and commercial mitigation, content restoration, storage, abatement (mold and asbestos), and damage repair service provider.

This is a scope of work agreement only. The remaining terms and conditions governing the parties' rights and obligations will be set forth in a written contract between the parties following the execution of this scope of work agreement.

The full construction cost estimate document shall become a part of the construction contract upon signature by both parties to the contract.

Listed below you will find a damage repair estimate detailing the work necessary to restore the above-mentioned property to a pre-loss condition. This estimate uses materials and workmanship of like kind and quality at rates determined by the industry standards which are reasonable and customary for the local market.

The line-item pricing in this estimate does not represent the actual cost of goods or services. Pricing for this project is based on the entire scope of work and may change after any modifications of the scope, quality, or scheduling constraints.

Any change to this original estimate, including, but not limited to material goods, code requirements, and hidden or unforeseen damages will be included in a separate estimate unless otherwise noted.

Change in Conditions: This estimate is based solely on the observations Compass was able to make with the structure in its current condition at the time this estimate was written. If additional unseen or concealed conditions are discovered once work has commenced Compass Construction will document and communicate the change in conditions to owner/ insurance carrier. Compass Construction will execute a change order and/or a supplement for any additional work. Change in condition may result in a temporary pause until an agreement can be reached.



#### **ESTIMATE**

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

## LAKELAND\_ASBESTOS Main Level

#### **Main Level**

DESCRIPTION	QTY	UNIT PRICE	TOTAL
GENERAL CONDITIONS			
1. Hazardous Waste/Mold Cleaning- Supervisory/Admin- per hour	80.00 HR @	109.80 =	8,784.00
Hazardous Waste / Asbestos - Supervisory/Admin- per hour			
OSHA requires the work and presence of a supervisor on asbestos abateme function is not optional. The bill includes a minimal charge for the supervi		ng Initial walk through	
with customer and Coordinate Asbestos and Lead Testing and Abatement.		ng minai waik unough	
2. Hazardous Waste/Asbestos Cleaning Technician - per hour	30.00 HR @	83.96 =	2,518.80
3. Equipment setup, take down, and monitoring (hourly charge)	28.00 HR @	83.96 =	2,350.88
Equipment setup, take down, and monitoring (hourly charge)			
- Initial Monitoring / Equipment Setup - Equipment Takedown (2.5) Unaccounted Job Labor:			
Additional technicians (10)			
Job documentation, billing, and processing (4)			
4. Neg. air fan/Air scrubXLrg (per 24 hr period)-No monit.	28.00 DA @	141.00 =	3,948.00
2 Negative Air Machines- Running length of project			
5. Add for HEPA filter (for negative air exhaust fan)	2.00 EA @	195.32 =	390.64
6. Ducting - lay-flat - Large	200.00 LF@	0.45 =	90.00
7. Add for HEPA filter (for canister/backpack vacuums)	2.00 EA @	73.85 =	147.70
8. Dumpster load - Approx. 40 yards, 7-8 tons of debris	1.00 EA @	763.40 =	763.40
9. Plastic dumpster liner - 40 yard	1.00 EA @	225.00 =	225.00
10. Plastic bag - used for disposal of contaminated items	30.00 EA @	3.40 =	102.00
11. Equipment decontamination charge - per piece of equipment	2.00 EA @	37.15 =	74.30
12. Hazardous waste hauling & disposal - (Bid Item)	1.00 EA @	1,895.00 =	1,895.00
SAFETY INVENTORY			
13. PAPR cartridge - HEPA only (single cartridge)	10.00 EA @	27.41 =	274.10
14. Add for personal protective equipment (hazardous cleanup)	84.00 EA @	13.43 =	1,128.12

Class 6 Height: 8' 8"

Door 2' 11 13/16" X 6' 7 1/8" Opens into MAIN\_HALLWAY Window 7' 11 3/8" X 4' Opens into Exterior

Window 7' 11 3/8" X 4' Opens into Exterior Window 7' 11 1/16" X 4' Opens into Exterior

DESCRIPTION QTY UNIT PRICE TOTAL



**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

#### **CONTINUED - Class 6**

DESCRIPTION	QTY UNIT PR		UNIT PRICE	TOTAL
DEMO / ABATEMENT PRACTICES:				
Install necessary critical barriers on all windows and doors. Set up Nega removal. Remove all carpet and all vinyl floor tile. Bag all asbestos contac Management.				
15. Containment Barrier/Airlock/Decon. Chamber	306.38	SF@	0.89 =	272.68
Critical barriers_ Doors, Windows Ect				
16. Clean the walls and ceiling	1,754.24	SF@	1.09 =	1,912.12
17. Vacuuming - (PER SF) - Heavy	835.11	SF@	0.21 =	175.37
18. Tear out non-salvageable carpet, cut/bag_	835.11	SF@	1.01 =	843.46
19. Tear out asbestos vinyl floor tile	835.11	SF@	3.05 =	2,547.09
20. Remove asbestos floor mastic	835.11	SF@	6.26 =	5,227.79
Removal of Glue Down carpet and Vinyl tile attached-				
21. Tear out baseboard covebase and bag for disp	112.66	LF@	1.89 =	212.93
Removal of cove base. this will be carefully removed to prevent as much w top of the base and peeled down.	all damage	as possible	e. It will be scored with	a knife at the
22. Apply asbestos fiber encapsulating compound	835.11	SF@	1.07 =	893.57
23. Final cleaning - construction - Commercial	835.11	SF @	0.28 =	233.83

Class 7 Height: 8' 8"

Window 7' 10 11/16" X 4' Opens into Exterior Window 7' 11 1/4" X 4' Opens into Exterior

Door 2' 11 11/16" X 6' 8 11/16" Opens into MAIN\_HALLWAY

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

8				
24. Containment Barrier/Airlock/Decon. Chamber	306.57	SF@	0.89 =	272.85
Critical barriers_ Doors, Windows Ect				
25. Clean the walls and ceiling	1,755.97	SF@	1.09 =	1,914.01
26. Vacuuming - (PER SF) - Heavy	836.26	SF@	0.21 =	175.61

# compass construction in

#### **Compass Construction Inc**

**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

#### **CONTINUED - Class 7**

DESCRIPTION		QTY	UNIT PRICE	TOTAL
27. Tear out non-salvageable carpet, cut/bag_	836.26	SF @	1.01 =	844.62
28. Tear out asbestos vinyl floor tile	836.26	SF@	3.05 =	2,550.59
29. Remove asbestos floor mastic	836.26	SF@	6.26 =	5,234.99
Removal of Glue Down carpet and Vinyl tile attached-				
30. Tear out baseboard covebase and bag for disp	112.76	LF@	1.89 =	213.12
Removal of cove base. this will be carefully removed to prevent as muctop of the base and peeled down.	ch wall damage a	ıs possible	e. It will be scored with	a knife at the
31. Apply asbestos fiber encapsulating compound	836.26	SF@	1.07 =	894.80
32. Final cleaning - construction - Commercial	836.26	SF@	0.28 =	234.15

Class 8 Height: 8' 8"

Door 3' 5/8" X 6' 8 5/16" Opens into MAIN\_HALLWAY

Window 7' 10 11/16" X 4' Opens into Exterior Window 8' 6 11/16" X 4' Opens into Exterior

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

Management.	Ü	•		
33. Containment Barrier/Airlock/Decon. Chamber	336.57	SF@	0.89 =	299.55
Critical barriers_ Doors, Windows Ect				
34. Clean the walls and ceiling	1,996.20	SF@	1.09 =	2,175.86
35. Vacuuming - (PER SF) - Heavy	986.49	SF@	0.21 =	207.16
36. Tear out non-salvageable carpet, cut/bag_	986.49	SF@	1.01 =	996.35
37. Tear out asbestos vinyl floor tile	986.49	SF@	3.05 =	3,008.79
38. Remove asbestos floor mastic	986.49	SF@	6.26 =	6,175.43
Removal of Glue Down carpet and Vinyl tile attached-				
39. Tear out baseboard covebase and bag for disp	123.40	LF @	1.89 =	233.23
Removal of cove base. this will be carefully removed to prevent as much wat top of the base and peeled down.	ıll damage a	as possible. It will b	be scored with a k	nife at the
40. Apply asbestos fiber encapsulating compound	986.49	SF@	1.07 =	1,055.54
41. Final cleaning - construction - Commercial	986.49	SF@	0.28 =	276.22
LAKELAND_ASBESTOS			9/6/2024	Page: 5



**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

#### **CONTINUED - Class 8**

DESCRIPTION **OTY** UNIT PRICE **TOTAL** Class 9 Height: 8' 8" Door 2' 11 9/16" X 6' 7 15/16" Opens into MAIN\_HALLWAY Window 7' 10 3/4" X 4' **Opens into Exterior** Window 7' 11 5/16" X 4' **Opens into Exterior** DESCRIPTION **QTY** UNIT PRICE TOTAL **DEMO / ABATEMENT PRACTICES:** Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management. 272.91 42. Containment Barrier/Airlock/Decon. Chamber 306.64 SF@ 0.89 =Critical barriers Doors, Windows Ect... 43. Clean the walls and ceiling 1.756.18 SF@ 1.09 =1.914.24 44. Vacuuming - (PER SF) - Heavy 836.26 SF@ 0.21 =175.61 836.26 SF@ 1.01 =844.62 45. Tear out non-salvageable carpet, cut/bag\_ 46. Tear out asbestos vinyl floor tile 836.26 SF@ 3.05 =2.550.59 47. Remove asbestos floor mastic 836.26 SF@ 6.26 =5,234.99 Removal of Glue Down carpet and Vinyl tile attached-48. Tear out baseboard covebase and bag for disp. -112.77 LF@ 1.89 =213.14 Removal of cove base, this will be carefully removed to prevent as much wall damage as possible. It will be scored with a knife at the top of the base and peeled down. 49. Apply asbestos fiber encapsulating compound 836.26 SF@ 1.07 =894.80 836.26 SF@ 50. Final cleaning - construction - Commercial 0.28 =234.15

Main Hallway Height: 8' 8"

Missing Wall - Goes to Floor 15' 7/16" X 7' 10" Opens into Exterior

Door 3' 1 3/8" X 6' 9 1/2" Opens into Exterior

Door 2' 11 11/16" X 6' 8 11/16" Opens into CLASS\_10







2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Door	3' 1 1/8" X 6' 9 7/8"		Opens into	Exterior	
Door	2' 11 11/16" X 6' 9 7/8"		_	CLASS_14	
Door	2' 11 13/16" X 6' 8 5/16"		_	CLASS_16_2	
Door	3' 1/8" X 6' 9 1/2"		Opens into		
Door	2' 10 5/8" X 6' 10 5/16"		Opens into		
Door	3' 1/4" X 6' 6 3/8"		_	CLASS_17	
Missing Wall - Goes to Floor	4' 11 3/4" X 7' 10"		Opens into		
Door	2' 11" X 7' 1/4"		Opens into		
Door	2' 11 13/16" X 6' 6 3/4"		Opens into		
Door	2' 10 7/8" X 6' 7 1/2"		Opens into		
Missing Wall - Goes to Floor	9' 5 1/4" X 7' 10"		Opens into		
Window	3' 11 15/16'' X 4'		Opens into		
Window	4' 3/16'' X 4'		Opens into		
Window	3' 1 5/8" X 3' 2 3/16"		Opens into		
Door	3' 1 1/16" X 6' 7 1/8"		Opens into		
Door	3' X 6' 6 3/4"		Opens into		
Door	3' 1/8" X 6' 6 3/4"		Opens into		
Door	2' 10 1/2" X 6' 8 5/16"		_	ELECTRICAL_R	
Door	2' 11 9/16" X 6' 7 15/16"		Opens into	CLASS_9	
Door	2' 11 11/16" X 6' 8 11/16	••	Opens into	CLASS_7	
Door	2' 11 13/16" X 6' 7 1/8"		Opens into	CLASS_6	
Door	3' 5/8" X 6' 8 5/16"		Opens into	CLASS_8	
Subroom: Main Hallway (1)					Height: 10'
Window	1' 5 3/4" X 6' 11 7/16"		Opens into	Exterior	
Window	9' 7" X 1' 10"		Opens into	Exterior	
Door	6' 2 1/8" X 7' 4 3/16"		Opens into	Exterior	
Window	1' 5 1/2" X 6' 10 11/16"		Opens into	Exterior	
Missing Wall - Goes to Floor	13' 7 15/16" X 8' 8"		Opens into	MAIN_HALLWAY	
Subroom: Main Hallway (2)					Height: 10'
Window	1' 5 1/16" X 7' 2"		Opens into	Exterior	
Window	9' 4" X 1' 10"		Opens into	Exterior	
Door	6' 1 7/8" X 7' 6"		Opens into	Exterior	
Window	1' 5" X 7' 2"		Opens into	Exterior	
Missing Wall - Goes to Floor	13' 7 13/16" X 8' 8"		Opens into	MAIN_HALLWAY	
DESCRIPTION			QTY	UNIT PRICE	TOTAL
Asbestos Activities					
51. Clean the walls and ceiling			5 SF@	1.09 =	8,529.09
52. Containment Barrier/Airlock/Decon. Chaml	per	7,824.8	5 SF @	0.89 =	6,964.12

LAKELAND\_ASBESTOS

Page: 7

9/6/2024



**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

#### **CONTINUED - Main Hallway**

DESCRIPTION		QTY	UNIT PRICE	TOTAL
53. Vacuuming - (PER SF) - Heavy	3,641.73	SF @	0.21 =	764.76
54. Floor protection - self-adhesive plastic film	3,641.73	SF@	0.51 =	1,857.28
55. Final cleaning - construction - Commercial	3,641.73	SF@	0.28 =	1,019.68

Class 10 Height: 8' 8"

Window 7' 10 11/16" X 4' Opens into Exterior Window 7' 11 1/4" X 4' Opens into Exterior

Door 2' 11 11/16" X 6' 8 11/16" Opens into MAIN\_HALLWAY

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

Managemeni.				
56. Containment Barrier/Airlock/Decon. Chamber	306.68	SF@	0.89 =	272.95
Critical barriers_ Doors, Windows Ect				
57. Clean the walls and ceiling	1,756.88	SF@	1.09 =	1,915.00
58. Vacuuming - (PER SF) - Heavy	836.85	SF@	0.21 =	175.74
59. Tear out non-salvageable carpet, cut/bag_	836.85	SF@	1.01 =	845.22
60. Tear out asbestos vinyl floor tile	836.85	SF@	3.05 =	2,552.39
61. Remove asbestos floor mastic	836.85	SF@	6.26 =	5,238.68
Removal of Glue Down carpet and Vinyl tile attached-				
62. Tear out baseboard covebase and bag for disp	112.80	LF@	1.89 =	213.19
Removal of cove base. this will be carefully removed to prevent as much top of the base and peeled down.	wall damage a	as possible. It	will be scored with a	knife at the
63. Apply asbestos fiber encapsulating compound	836.85	SF@	1.07 =	895.43
64. Final cleaning - construction - Commercial	836.85	SF @	0.28 =	234.32

Class 14 Height: 8' 8"

Window 11' 10 3/16" X 4' Opens into Exterior



**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Door	2' 11 11/16" X 6' 9 7/8"		Opens into MAIN_HALLWAY	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
DEMO / ABATEMENT PRACTICES:				
Install necessary critical barriers on all window removal. Remove all carpet and all vinyl floor ti. Management.				
65. Containment Barrier/Airlock/Decon. Chambe	er 284.82	SF@	0.89 =	253.49
Critical barriers_ Doors, Windows Ect				
66. Clean the walls and ceiling	1,560.08	SF@	1.09 =	1,700.49
67. Vacuuming - (PER SF) - Heavy	705.60	SF@	0.21 =	148.18
68. Tear out non-salvageable carpet, cut/bag_	705.60	SF@	1.01 =	712.66
69. Tear out asbestos vinyl floor tile	705.60	SF@	3.05 =	2,152.08
70. Remove asbestos floor mastic	705.60	SF@	6.26 =	4,417.06
Removal of Glue Down carpet and Vinyl tile atta	ched-			
71. Tear out baseboard covebase and bag for dis	sp 103.43	LF@	1.89 =	195.48
Removal of cove base. this will be carefully remotop of the base and peeled down.	oved to prevent as much wall damage	as possibl	le. It will be scored with a	knife at the
72. Apply asbestos fiber encapsulating compoun	d 705.60	SF@	1.07 =	754.99
73. Final cleaning - construction - Commercial	705.60	SF @	0.28 =	197.57

Class 16		Height:	8' 8''
Door	2' 11 13/16" X 6' 8 5/16"	Opens into MAIN_HALLWAY	

Window 12' 5/16" X 4' Opens into Exterior Door 2' 8 5/8" X 6' 8 5/16" Opens into Exterior

Subroom: Class 16 (1) Height: 7' 8"

Door 2' 11 11/16" X 6' 8 5/16" Opens into Exterior

Missing Wall - Goes to Floor 13' 4 11/16" X 7' 5" Opens into CLASS\_16\_2

Missing Wall - Goes to Floor 2' 5 1/2" X 7' 5" Opens into CLASS\_16\_2

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

74. Containment Barrier/Airlock/Decon. Chamber	403.84	SF@	0.89 =	359.42
Critical barriers_ Doors, Windows Ect				
75. Clean the walls and ceiling	2,354.34	SF@	1.09 =	2,566.23
76. Vacuuming - (PER SF) - Heavy	1,142.82	SF@	0.21 =	239.99
LAKELAND_ASBESTOS			9/6/2024	Page: 9

## **Compass Construction Inc**

**ESTIMATE** 

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

#### **CONTINUED - Class 16**

DESCRIPTION		QTY	UNIT PRICE	TOTAL
77. Tear out non-salvageable carpet, cut/bag_ 2	87.89	SF@	1.01 =	290.77
78. Tear out asbestos vinyl floor tile 1,1	42.82	SF@	3.05 =	3,485.60
79. Remove asbestos floor mastic 2	87.89	SF@	6.26 =	1,802.19
Removal of Glue Down carpet and Vinyl tile attached-				
80. Tear out baseboard covebase and bag for disp	46.71	LF@	1.89 =	277.28
Removal of cove base, this will be carefully removed to prevent as much wall dat top of the base and peeled down.	mage a	as possible.	It will be scored with a	knife at the
81. Apply asbestos fiber encapsulating compound 2	87.89	SF@	1.07 =	308.04
82. Final cleaning - construction - Commercial 1,1	42.82	SF@	0.28 =	319.99

Class 17 Height: 8' 8"

Window 11' 10 1/16" X 4' Opens into Exterior

Door 3' 1/4" X 6' 6 3/8" Opens into MAIN\_HALLWAY

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

Management.	Ü			
83. Containment Barrier/Airlock/Decon. Chamber	270.41	SF@	0.89 =	240.66
Critical barriers_ Doors, Windows Ect				
84. Clean the walls and ceiling	1,446.12	SF@	1.09 =	1,576.27
85. Vacuuming - (PER SF) - Heavy	634.88	SF@	0.21 =	133.32
86. Tear out non-salvageable carpet, cut/bag_	634.88	SF@	1.01 =	641.23
87. Tear out asbestos vinyl floor tile	634.88	SF@	3.05 =	1,936.38
88. Remove asbestos floor mastic	634.88	SF@	6.26 =	3,974.35
Removal of Glue Down carpet and Vinyl tile attached-				
89. Tear out baseboard covebase and bag for disp	98.32	LF@	1.89 =	185.82
Removal of cove base. this will be carefully removed to prevent as much very top of the base and peeled down.	vall damage a	as possible. It w	ill be scored with	a knife at the
90. Apply asbestos fiber encapsulating compound	634.88	SF@	1.07 =	679.32
91. Final cleaning - construction - Commercial	634.88	SF @	0.28 =	177.77



#### **ESTIMATE**

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Height: 8'

Door 1' 11 5/16" X 6' 9 1/2" Opens into HEALTH\_ROOM\_

Door 2' 6 11/16" X 6' 8 11/16" Opens into Exterior

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

172011ugentetti			
92. Containment Barrier/Airlock/Decon. Chamber	122.16 SF @	0.89 =	108.72
Critical barriers_ Doors, Windows Ect			
93. Clean the walls and ceiling	501.86 SF @	1.09 =	547.03
94. Vacuuming - (PER SF) - Heavy	135.37 SF @	0.21 =	28.43
95. Tear out asbestos vinyl floor tile	135.37 SF @	3.05 =	412.88
96. Remove asbestos floor mastic	135.37 SF @	6.26 =	847.42
Removal of Glue Down carpet and Vinyl tile attached-			
97. Tear out wood trim	45.11 LF @	0.53 =	23.91
98. Apply asbestos fiber encapsulating compound	135.37 SF @	1.07 =	144.85
99. Final cleaning - construction - Commercial	135.37 SF @	0.28 =	37.90

Health Room Toilet Height: 9' 9"

Door 1' 11 5/16" X 6' 9 1/2" Opens into HEALTH\_ROOM

DESCRIPTION QTY UNIT PRICE TOTAL

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

100. Clean the walls and ceiling 130.06	5 SF @	1.09 =	141.77
101. Vacuuming - (PER SF) - Heavy 11.02	SF @	0.21 =	2.31
102. Remove Toilet_ Remove toilet 1.00	EA @	89.95 =	89.95
103. Tear out asbestos vinyl floor tile 11.02	SF @	3.05 =	33.61
104. Remove asbestos floor mastic 11.02	SF @	6.26 =	68.99
Removal of Glue Down carpet and Vinyl tile attached-			
105. Tear out wood trim	LF @	0.53 =	6.16
106. Apply asbestos fiber encapsulating compound 11.02	SF @	1.07 =	11.79
107. Final cleaning - construction - Commercial 11.02	SF @	0.28 =	3.09



Door

#### **Compass Construction Inc**

**ESTIMATE** 

Opens into MAIN\_HALLWAY

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

Electrical Room	Height: 9' 7"
-----------------	---------------

DESCRIPTION	OTY	UNIT PRICE	TOTAL

2' 10 1/2" X 6' 8 5/16"

#### **DEMO / ABATEMENT PRACTICES:**

Install necessary critical barriers on all windows and doors. Set up Negative pressure rooms in each class room during asbestos removal. Remove all carpet and all vinyl floor tile. Bag all asbestos containing materials and haul off to Graham Road Waste Management.

108. Containment Barrier/Airlock/Decon. Chamber	165.75 SF @	0.89 =	147.52
Critical barriers_ Doors, Windows Ect			
109. Clean the walls and ceiling	660.43 SF @	1.09 =	719.87
110. Vacuuming - (PER SF) - Heavy	163.19 SF @	0.21 =	34.27
111. Remove Toilet_ Remove toilet	1.00 EA @	89.95 =	89.95
112. Tear out asbestos vinyl floor tile	163.19 SF @	3.05 =	497.73
113. Remove asbestos floor mastic	163.19 SF @	6.26 =	1,021.57
Removal of Glue Down carpet and Vinyl tile attached-			
114. Tear out wood trim	51.02 LF @	0.53 =	27.04
115. Apply asbestos fiber encapsulating compound	163.19 SF @	1.07 =	174.61
116. Final cleaning - construction - Commercial	163.19 SF @	0.28 =	45.69

#### **Labor Minimums Applied**

DESCRIPTION	QTY	UNIT PRICE	TOTAL
117. Plumbing labor minimum	1.00 EA@	128.11 =	128.11

#### **Grand Total Areas:**

12,740.66	SF Walls	10,765.64	SF Ceiling	23,506.30	SF Walls and Ceiling
10,765.64	SF Floor	1,196.18	SY Flooring	1,496.14	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	1,720.03	LF Ceil. Perimeter
10,765.64	Floor Area	11,197.90	Total Area	12,740.66	Interior Wall Area
7,771.20	Exterior Wall Area	920.17	Exterior Perimeter of		
			Walls		
	~ .				
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		



# **ESTIMATE**

2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

# **Summary for Dwelling**

Line Item Total	140,708.35
Material Sales Tax	793.39
Subtotal	141,501.74
Overhead	14,150.24
Profit	14,150.24
Replacement Cost Value Net Claim	\$169,802.22 \$169,802.22
	<del></del>

Daniel Burns Estimator







2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

# Recap by Room

**Estimate: LAKELAND\_ASBESTOS** 

Area: Main Level	22,691.94	16.13%
Class 6	12,318.84	8.75%
Class 7	12,334.74	8.77%
Class 8	14,428.13	10.25%
Class 9	12,335.05	8.77%
Main Hallway	19,134.93	13.60%
Class 10	12,342.92	8.77%
Class 14	10,532.00	7.48%
Class 16	9,649.51	6.86%
Class 17	9,545.12	6.78%
Health Room	2,151.14	1.53%
Health Room Toilet	357.67	0.25%
Electrical Room	2,758.25	1.96%
Area Subtotal: Main Level	140,580.24	99.91%
Labor Minimums Applied	128.11	0.09%
Subtotal of Areas	140,708.35	100.00%
Total	140,708.35	100.00%








2503 E. Riverside Spokane WA 99202 509-532-0055

Fed Tax ID: 91-1947756

# **Recap by Category**

O&P Items	Total	%
CLEANING	5,275.11	3.11%
GENERAL DEMOLITION	71,592.00	42.16%
HAZARDOUS MATERIAL REMEDIATION	60,881.61	35.85%
PLUMBING	128.11	0.08%
WATER EXTRACTION & REMEDIATION	2,831.52	1.67%
O&P Items Subtotal	140,708.35	82.87%
Material Sales Tax	793.39	0.47%
Overhead	14,150.24	8.33%
Profit	14,150.24	8.33%
Total	169,802.22	100.00%





# Main Level



9/23/2024

TO: Christine Anderson

**Project Lead** 

**Lakeland Joint School District #272** 

(208)-687-2248

canderson@lakeland272.org

FROM: Cody Taylor

Tennis Operations Manager Beynon Sports Surfaces Inc.

503-539-7930

CTaylor@beynonsports.com

# **Lakeland HS 5 Tennis Courts**

Beynon Sports is pleased to present this proposal. Court must be constructed within ASBA standards to provide a warranty.

	OPTION #1 TENNIS COURT RESURFACING:
Scope:	<ul> <li>Remove unadheared Armor @ appx 1,440 linear feet.</li> <li>High pressure-wash the entire court surface as needed.</li> <li>Flood court surface and mark low areas that hold water over the depth of a nickel. Proper slope must be present to alleviate birdbaths.</li> <li>Patch and repair low areas, fill *cracks. Please note that cracking will return.</li> <li>Apply one coat of Acrylic Resurfacer to the entire court surface.</li> <li>Apply two textured Color Filler coats to the entire court surface.</li> <li>Apply one textured Color Finish coat to the entire court surface.</li> <li>Lines will be accurately laid out, taped, primed, and painted with two coats of Textured Line Paint.</li> <li>Striping to include 5 tennis courts.</li> </ul>
Cost:	<u>\$ 53,140.00</u>
Add Alt #1:	Furnish and install appx 2,000 linear feet of Guardian Crack Repair System.
Cost:	<u>\$ 74,620.00</u>

	OPTION #2 REPAIRS:
Scope:	<ul> <li>Remove center 6" of existing Armor @ appx 1,440 linear feet.</li> <li>High pressure-wash the court surface as needed.</li> <li>Fill *cracks at appx 2,000 linear feet. Please note that cracking will return.</li> <li>Apply one coat of Acrylic Resurfacer to repaired areas only.</li> <li>Apply two textured Color Filler coats to repaired areas only.</li> <li>Apply one textured Color Finish coat to repaired areas only.</li> <li>Replace lines as needed.</li> <li>Please note that repairs will not match existing, work will look like patches.</li> </ul>
Cost:	\$ 34,384.00



#### **Exclusions:**

- This quotation excludes any design costs, engineered or stamped drawings, bonds, union or labor law levies, agency
  approval or associated fees, protection of sports surface after completion, permits(owners responsibility),
  moving/removal/replacing any utilities to include sprinklers, remediation of unsuitable soils, multiple mobilizations, logos
  or other unforeseen costs.
- Asphalt is manufactured with gravel, sand, and liquid petroleum. Most plants produce asphalt using gravel mined from hillsides. Mined gravel may contain clay balls and iron causing small insignificant voids and rust spots that may migrate to the acrylic surface. Since the producer's source of aggregate may vary from time to time, it is impossible to predict whether a particular batch of asphalt from a producer will contain clay balls or iron. If clay balls and or rust spots develop they will not hinder play or hurt the structural integrity of the court and are almost always eliminated after the first resurfacing. The most common problem with asphalt tennis courts is pavement cracking. Cracking in asphalt is caused, at least in part, by the natural tendency of asphalt to shrink as it weathers, oxidizes and ages. In addition, asphalt loses its flexibility as it ages, making it more brittle. Since shrinking and becoming more brittle with age are properties of the material, cracking in asphalt tennis courts is inevitable. This condition is beyond the control of Beynon Sports, its suppliers and sub-contractors. Therefore Beynon Sports will not assume any responsibility if such conditions appear.
- For concrete courts, surface coatings will not solve or eliminate reactive aggregates or ASR in the slab. This condition is beyond the control of Beynon Sports, its suppliers, and sub-contractors. Therefore, Beynon Sports will not assume any responsibility if such conditions appear.
- Unbound multi-layer surface coatings, bubbles, and/or peeling cannot be determined until the resurfacing preparation work has begun. If encountered, surfacing removal will be required at an additional cost.
- Standing water may not be eliminated due to waves in the profile of the courts and/or lack of slope. Staining, peeling, and delamination in these areas are not covered under warranty.
- Due to the uncertainty and volatility in raw materials supplies, material costs, and shipping delays, this proposal is valid for 30 days.
- \*Cracks will appear/reappear with ground movement and temperature change cycles. Yearly maintenance on your part will be required to re-seal small cracks. **There is no warranty on crack repair.**
- Fractures on membrane are to be expected.
- Suitable water source must be provided by owner.
- · Pricing does not include removal of boulders, foundations, or any other buried unforeseen impediments.

If you have any questions, please call me at 503-539-7930.

Sincerely,

Cody Taylor Tennis Operations Manager Beynon Sports Surfacing, Inc.



If you agree with the terms and conditions of this proposal please initial next to approved option(s), indicate total contract value below, sign and fax/mail back.

We hereby accept the conditions of this offer stipulated herein.

CONTRACT \$		
NAME OF PROJECT:		
Signed this	_day of	, 2024
Signature:		
Printed Name:		
Billing Name (if different):		
Billing Address:		
City:	State:	Zip Code:
Phone Number:		
Colors Inside	Outside	
Beynon Sports Surfaces, Inc.		
Signed this	_day of	, 2024
Accepted by:		
Printed Name:		
Materials remain property of Bey		
Purchase orders/Contracts shou Beynon Sports Surfaces, Inc. Attention: Peter Robison 19600 SW 129 <sup>th</sup> Avenue Suite A Tualatin, Oregon 97062 Tel: 800-423-5875 ext. 238 Fax: PRobison@beynonsports.com		

The purchase price shall be payable to the contractor by way of check in accordance with the payment schedule. Contractor will issue an invoice to customer upon the occurrence of each of the events listed above, and payment of each invoice is due within ten (10) days following the date of the applicable invoice.

Be sure to visit our website at www.beynonsports.com.