

**JOHN S. GRAVES & ASSOCIATES, INC.  
ARCHITECTS**

202 HORNBY PLACE  
UVALDE, TEXAS 78801

Phone (830) 278-6677  
Fax (830) 278-6679

**ARCHITECT'S  
FIELD REPORT**

OWNER [ ]  
ARCHITECT [X]  
CONSULTANT [ ]  
FIELD [ ]


**PROJECT:** A NEW STORAGE BULDING, BRACKETT I.S.D.  
BRACKETTVILLE, TEXAS  
**CONTRACTOR:** PIONEER CONCEPTS, LP  
**OWNER:** BRACKETT I.S.D.

**DATE:** 09/07/06 **TIME:** 2:00 PM

**PRESENT AT SITE:** JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC.  
RICHARD & JAVI - BRACKETT I.S.D.

1. Reused overhead door is binding on track near top. Perhaps bend top or chamfer top to clear door panel.
2. Install precast concrete splash blocks.
3. Repair 2 roof leaks @ ridge in center.
4. Close gap at top of new overhead door.

REPORT BY:

  
John S. Graves, Jr.