

MAINTENANCE REPORT SEPTEMBER 2020

Submitted by: Reid Reagan

Maintenance staff has been busy installing walk thru temperature check stations with fever temperature detection at the buildings. Also set up heavy duty air cleaners with 4 stage filters, and a UV light to remove harmful particles in the air.

Groundskeepers have been painting football field, also winterizing sprinkler systems, blowing out water sprinkler systems with air to prevent freezing and remove all pumps/tanks. Doing preventive maintenance on the heating systems, replacing leaking pressure relief valves and faulty ignitors, also had Case loader, skidsteer and snow plows serviced for winter.

HIGH SCHOOL:

Repaired faulty fire panel at main entrance, bare wires causing keypad to alarm with ground fault error.

KWB:

Replaced broken windows throughout school, replace rusted out metal security door to the east entrance to the gymnasium.

BES:

Replaced faulty thermalcoupler, boiler.

VC:

Installed fire protection magnetic door holders, release (shut) doors with fire control panel. Installing new LED lighting throughout the school.

NAPI:

Replace rusted out metal security door to the bottom entrance to cafeteria/kitchen.