South San Antonio Coulth an The second the

SOUTH SAN ANTONIO INDEPENDENT SCHOOL DISTRICT

Agenda Item Summary

Meeting Date: June 27, 2016
Purpose: Report Only Recognition Discussion/ Possible Action
Presenter(s): Dr. Abelardo Saavedra, Superintendent
Itam Title
Item Title:
Discussion and possible action to include in the 2016-17 Budget the sale of \$10 million in Maintenance Notes.
Description:
At the April 7, 2016 budget workshop, Administration reported on an option to issue \$10,000,000 of maintenance notes for facility repairs and improvements using the 3 cents excess from the debt service fund rebated to the general fund for the annual payment.
The \$10,000,000 will address the schools identified with urgent maintenance needs in the facility needs assessment report from 2015: repairs that reduce or eliminate safety hazards, repairs that are needed to preserve the building's integrity, replacements or repairs that will save money and conserve energy, and remodeling that will provide essential instructional facilities.
The sale of the maintenance notes will provide the opportunity to leverage \$1 million to \$10 million that would be used for facilities.
District Goal:
Goal 6 We will promote and ensure a safe and secure learning environment for all students.
Funding Budget Code and Amount: CFO Approval
APPROVAL ROUTE SIGNATURE DATE Principal/Director: Executive Director: Chief Administrator: Superintendent:

2016-17 Facility Improvements Maintenance Notes Initiative

South San Antonio Independent School District

July 27, 2016

Facility Repairs & Improvements Initiative

- Facility Improvements Assessment History:
- April 2013 Board Approved Hollon & Cannon to Conduct District wide Roof Assessment
- February 2015 Board Approved Garza Bomberger to Conduct District wide Facility Assessment
- May 2015 Presentation Facility Assessment Report Totaling Needs of \$195,834,800
- April 7, 2016 Bond Presentation by Mr. Joe Wisnowski, Mr. Dan Casey, Mr. Richard Acosta and Mr. Dan Martinez
- June 27, 2016 Presentation of \$10 Million Urgent Facility needs Identified from District Wide Facility Assessment Report

• Urgent Identified Facility Needs:

•	Roof	Replacement	ጼ	Renairs	\$2,259,947	
	11001	neblacement	Œ	neballs	36.633.371	

HVAC Replacement \$3,079,300

Interior Repairs & Painting \$3,350,314

• Fencing Repairs & Replacements \$400,000

2016-17 Facility Improvements Maintenance Notes Initiative Summary

Schools / Facilities	ORG	ROOF REPLACEMENT & REPAIRS	RI	HVAC EPLACEMENT		INTERIOR REPAIRS & PAINTING	R	FENCING REPAIRS & EPLACEMENTS	CA	MPUS TOTAL
Armstrong Elementary	110	\$ 34,806	\$	302,100	\$	170,309	\$	30,000	\$	537,215
Athens Elementary	101	\$ 265,906	\$	270,300	\$	207,389	\$	25,000	\$	768,595
Benavi dez Elementary	113	\$ 67,940	\$	983,150	\$	299,919	\$	-	\$	1,351,009
Carrillo Elementary	112	\$ 2,350	\$	53,000	\$	157,733	\$	15,000	\$	228,083
Dwight Middle School	041	\$ 297,111	\$	10,600	\$	432,209	\$	20,000	\$	759,920
Five Palms Elementary	109	\$ -	\$	373,650	\$	153,510	\$	40,000	\$	567,160
Hutchins Elementary	104	\$ 31,035	\$	100,700	\$	208,217	\$	40,000	\$	379,952
Kazen Middle School	043	\$ 93,264	\$	148,400	\$	298,869	\$	50,000	\$	590,533
Kindred Elementary	105	\$ 36,190	\$	26,500	\$	162,390	\$	50,000	\$	275,080
Madla Elementary	108	\$ 27,766	\$	148,400	\$	172,985	\$	30,000	\$	379,151
Palo Alto Elementary	106	\$ 9,225	\$	92,750	\$	231,767	\$	50,000	\$	383,742
Price Elementary	107	\$ 557,411	\$	159,000	\$	170,011	\$	20,000	\$	906,422
Shepard Middle School	042	\$ 75,000	\$	10,600	\$	299,715	\$	30,000	\$	415,315
South San High School - Career Ed/Athletic Center	001	\$ 755,668	\$	386,900	\$	-	\$	-	\$	1,142,568
Zamora Middle School	044	\$ 6,275	\$	13,250	\$	385,292	\$	-	\$	404,817
TOTAL		\$ 2,259,947	\$	3,079,300	\$	3,350,314	\$	400,000	\$	9,089,561
			Τ	Engine	eri	ng/Consulti	ing	g Fees	\$	910,439
				Total P	ro	ject Summa	ry	Cost	\$	10,000,000
*Maintenance Notes to be Paid from 3 cents Tax Credit from the bond paying agent account.			,	*Total Maint	en	ance Notes	T	o be issued	\$	10,000,000

Armstrong Elementary

Roof Replacement and Repairs: \$ 34,806 Estimate

• 6 of 19 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane is aging with visible deterioration and metal roof panels are surface rusting.

HVAC Replacement: \$ 302,100 Estimate

• 23 out of the 38 units (114 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 170,309 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$30,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$537,215

Athens Elementary

Roof Replacement and Repairs: \$ 265,906 Estimate

• 14 of 23 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane is aging with visible deterioration and has no more serviceable life.

HVAC Replacement: \$ 270,300 Estimate

• 28 out of the 69 units (102 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 207,389 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 25,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 768,595

Benavidez Elementary

Roof Replacement and Repairs: \$ 67,940 Estimate

• 10 of 21 existing roof sections has been identified as requiring immediate replacement or repairs. Rusting observed at numerous metal roof penetrations, valleys and ridge cap visible open to water intrusion.

HVAC Replacement: \$ 983,150 Estimate

• 99 out of the 123 units (371 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 299,919 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Total Cost Estimate: \$ 1,351,009

Carrillo Elementary

Roof Replacement and Repairs: \$ 2,350 Estimate

6 of 9 existing roof sections has been identified as requiring immediate replacement or repairs. Screws backing out at ridge caps and control joints splitting open to water intrusion.

Painting/Trim/Ceiling: \$ 157,733 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 15,000 Estimate

Additional fencing is required for security and safety

HVAC Replacement: \$ 53,000 Estimate

4 out of the 48 units (20 tons)

Total Cost Estimate: \$ 228,083

Dwight Middle School

Roof Replacement and Repairs: \$ 297,111 Estimate

• 9 of 11 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane flashing is aging with visible deterioration and nearing the end of serviceable life. Fasteners at metal ridge are backing out.

Painting/Trim/Ceiling: \$ 432,209 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 20,000 Estimate

Additional fencing is required for security and safety

HVAC Replacement: \$ 10,600 Estimate

4 out of the 31 units (4 tons)

Total Cost Estimate: \$ 759,920

Five Palms Elementary

HVAC Replacement: \$ 373,650 Estimate

• 28 out of the 38 units (141 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 153,510 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 40,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 567,160

Hutchins Elementary

Roof Replacement and Repairs: \$ 31,035 Estimate

• 12 of 22 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane is aging with visible deterioration. Asphalt shingles observed to be aged and missing.

HVAC Replacement: \$ 100,700 Estimate

• 4 out of the 59 units (38 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 208,217 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 40,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 379,952

Kazen Middle School

Roof Replacement and Repairs: \$ 93,264 Estimate

• 12 of 32 existing roof sections has been identified as requiring immediate replacement or repairs. Roof flashing has deteriorated. Roof deck and asphalt shingles observed to be worn, damaged and missing.

HVAC Replacement: \$ 148,400 Estimate

• 14 out of the 74 units (56 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 298,869 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 50,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 590,533

Kindred Elementary

Roof Replacement and Repairs: \$ 36,190 Estimate

 9 of 16 existing roof sections has been identified as requiring immediate replacement or repairs. Roof flashing observed blistered and deteriorated. Roof deck observed worn and damaged. Asphalt shingles observed to be damaged and missing.

Painting/Trim/Ceiling: \$ 162,390 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 50,000 Estimate

Additional fencing is required for security and safety

HVAC Replacement: \$ 26,500 Estimate

• 1 out of the 44 units (10 tons)

Total Cost Estimate: \$ 275,080

Madla Elementary

Roof Replacement and Repairs: \$ 27,766 Estimate

8 of 21 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane flashing is aging with visible deterioration and nearing the end of serviceable life. Metal panels are open and exposed open to water intrusion.

HVAC Replacement: \$ 148,400 Estimate

• 8 out of the 50 units (56 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 172,985 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement

Fencing: \$ 30,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 379,151

Palo Alto Elementary

Roof Replacement and Repairs: \$ 9,225 Estimate

• 7 of 33 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane flashing is aging with visible blistering and deterioration.

HVAC Replacement: \$ 92,750 Estimate

• 3 out of the 49 units (35 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 231,767 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 50,000 Estimate

Additional fencing is required for security and safety

Total Cost Estimate: \$ 383,742

Price Elementary

Roof Replacement and Repairs: \$ 557,411 Estimate

• 16 of 20 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane is aging with visible blistering and deterioration open to water intrusion.

Painting/Trim/Ceiling: \$ 170,011 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 20,000 Estimate

Additional fencing is required for security and safety

HVAC Replacement: \$ 159,000 Estimate

• 20 out of the 60 units (60 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Total Cost Estimate: \$ 906,422

Shepard Middle School

Roof Replacement and Repairs: \$ 75,000 Estimate

4 of 23 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane is aging with visible blistering and deterioration open to water intrusion.

Painting/Trim/Ceiling: \$ 299,715 Estimate

- Facility has not had interior painting in 5 to 10 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Fencing: \$ 30,000 Estimate

Additional fencing is required for security and safety

HVAC Replacement: \$ 10,600 Estimate

1 out of the 36 units (4 tons)

Total Cost Estimate: \$ 415,315

South San High School

Career Education & Athletic Center Buildings

Roof Replacement and Repairs: \$ 755,668 Estimate

• 5 of 5 existing roof sections has been identified as requiring immediate replacement or repairs. Roof membrane flashing is aging with visible deterioration and nearing the end of serviceable life.

HVAC Replacement: \$ 386,900 Estimate

• 28 out of the 223 units (146 tons)

Total Cost Estimate: \$ 1,142,568

Zamora Middle School

Roof Replacement and Repairs: \$ 6,275 Estimate

• 8 of 18 existing roof sections has been identified as requiring immediate replacement or repairs. Metal roof panels observed damaged and open to water intrusion. Pipe penetration boots beyond its useful life.

HVAC Replacement: \$ 13,250 Estimate

• 1 out of the 24 units (5 tons) have been identified as requiring immediate replacement due to units not running efficiently due to rusted fan motors, belts cracked, frozen systems, hail damage, age (over 10 years old).

Painting/Trim/Ceiling: \$ 385,292 Estimate

- Facility has not had interior painting in 10 to 15 years
- Damaged/Stained ceiling tiles caused by roof leaks need replacement
- Damaged trim work need replacement

Total Cost Estimate: \$ 404,817

South San Antonio Independent School District Board Action Calendar 10,000,000* Maintenance Tax Notes, Series 2016

Date	Action	Responsibility			
August 17	Presentation of Plan and Calendar to the Board of Trustees	Jesus Salazar, Richard Acosta			
September 19	Board Meeting to Approve Bond Sale	Richard Acosta, Dan Martinez			
October 19	Approve & Execute Bond Purchase Agreement & Certificates	Jesus Martinez, Richard Acosta, Dan Martinez			
October 26	Bond Closing	Richard Acosta, Dan Martinez			

End of Presentation

Questions?