

FACILITIES/CONSTRUCTION REPORT FEBRUARY 2021

BMS Renovation/Addition:

2-19 Windy, cold. Wadsworth replaced air metering valve on #2 BLR, and per manufacturers suggestion (Lochinvar) drilled 1/2" holes in intake pipe just below the inside ceiling on all 3 boilers (mix warm air with outside air). Also replaced pressure sensor on glycol feeder, 1 worker. Hagenstad touch-up painting restrooms new addition, 1 worker.

2-25 Windy, cold. Systems NW installed clocks/speakers in gym, 2 workers. Great Falls Overhead Door installed new drive system for automatic rollup doors in kitchen, 2 workers.

2-26 Calm, cool. Wadsworth replaced sensor for water booster pumps, 1 worker.