## **MEMORANDUM**

TO: NWABSD Board of Education

Members

DATE: January 2025

NUMBER:

Work Session Items revision

FR: Office of the Superintendent

**SUBJECT:** 

a) Property Services Report

Property Services Director, Donavon Watkins reports on the following:

AMBLER Boiler stack fire in gym. Building is temporarily closed. Plumber is working on getting heat up and

running.

BUCKLAND 2 Duplexes and two bedroom house framed in, windows in, exterior painted, porches on, boiler

rooms finished, ready for plumbing rough in since October. New flooring in 1 bedroom unit

DEERING Installed 4 new windows in classrooms, Insulation foamed entire bottom of school

KIANA nothing new to report

KIVALINA Still working on getting plumbing system to function properly

KOBUK fixed broken fire sprinkler line

KOTZEBUE New boiler burners in KMS, plumbing fixed in ATC after freeze up, Patched and painted cracks and

damaged walls throughout building ATC. Remodel 1 bedroom unit adult dorm attendant and fixed

glycol leak in Star Dorm

NOATAK Carpenters installed a waynescot around the bottom of gym to cover walls and protect from further

damage, They also patched and painted cracks and damaged walls throughout entire school, leveled a pump building, skirted it, painted it and installed stairs, adjusted doors and installed a classroom

sound system.

NOORVIK New porch and stairs on 6 plex, leveled and painted main stairwell, built new trash bin for housing,

painted all interior window walls where new windows were installed. Plumber thawed freeze up,

patched sewer lines and glycol leak in housing

SELAWIK Traffic accident took out Principals porch. New porch and stairs on unit. New flooring in two

housing units. Patch and paint cracked and damaged walls throughout school. BPO thawed frozen

plumbing

SHUNGNAK Plumber installed new water heater in Teacher housing

To summarize, The maintenance Department is making leaps and bounds to make sure your sites are getting the support you need to continue seamless operation.

We will respond immediately and act promptly to keep our buildings in top shape.