

## JANUARY WEATHER REPORT

LOTS AND LOTS OF SNOW REMOVAL  
SHORTAGE OF ICE MELT

### **FREEZING TEMPS**

FAN MOTOR FAILURE IN BOILER @ DSC  
ROOFTOP UNITS ACROSS THE DISTRICT FAILING BECAUSE OF FROZEN GAS REGULATORS FREEZING  
CONTROLS FAILURES  
ROOFTOP UNITS ACROSS THE DISTRICT FAILING BECAUSE OF FROZEN GAS REGULATORS FREEZING  
BURNERS BREAKING BECAUSE OF TEMPERATURE  
IGNITION CONTROLS BREAKING DUE TO TEMPERATURE

### **FROZEN PIPES**

HEYBURN KITCHEN HANDWASH SINK  
FROZEN WATER METER AT THE BUS GARAGE  
FROZEN WATER REST ROOM MAINTENANCE  
FIRE SUPPRESSION

### **FLOORING INTERIOR**

MAINTENANCE BUILDING  
PAUL LIBRARY  
MINICO DIESEL SHOP

### **ROOF LEAKS AT VARIOUS LOCATIONS**

### **PLAYGROUNDS FLOODING**

### **PUMPING TO PREVENT FLOODING**

MAINTENANCE  
HEYBURN  
RUPERT  
FOOD SERVICE

THIS IS NOT ALL INCLUSIVE

# JANUARY WEATHER REPORT

NG

NG