

Transportation and Maintenance Report

Report for December Meeting 2025

Transportation

1. Bus #54, Transmission filter service.

Pacific High School

1. Run network cable for staff room copier.
2. Replace broken faucet in art room.
3. Install deadbolt lock on garage door at track storage.
4. Install security lights on each end of track building.
5. Replace door and trim, entrance door to track concessions.
6. Surplus items sold on public surplus: score board and rubber mats from weight room.
All items have been picked up.
7. Heater installed in metal shop.
8. New cellular communicators installed into security/alarm system.