

MAINTENANCE REPORT AUGUST 2025

Submitted by: Reid Reagan

Maintenance staff has been busy with painting of parking lot spaces, handicap parking, and crosswalks. Groundskeepers have been busy watering, trimming and mowing lawns. Doing preventive maintenance on the fire alarm & sprinkler/security alarm systems, both Summit Fire Protection and Interstate Alarms did annual inspections of the buildings.

BHS:

Glacier Electric augered 42 post holes @ 5' deep, concrete 16' posts in holes with anchors concreted in 5' holes, install wind fence onto posts. Blackfeet tribe sprayed for noxious weeds. Western Sports Flooring deep clean gym floors, reseal and recoat.

BMS:

Building has been hit by vandalism, broken surveillance camera, broken sprinkler heads and shed door. Graffiti on the walls and on the roof, and shed which has been cleaned off or painted over. Western Sports Flooring deep clean gym floors, reseal and recoat.

BES:

Glacier Electric replaced broken power pole and weakened power line, dug new line to transformer and replaced old cable, power and internet restored. Replace crumbling concrete sidewalk. Western Sports Flooring deep clean gym floors, reseal and recoat.

BULLSHOE-KWB:

Replaced broken windows throughout the building, (3). MSEC installed 6' safety wall padding on the ends of courts.

NAPI:

Western Sports Flooring deep clean gym floor, reseal and recoat. Replace crumbling concrete steps/sidewalk at gym main entrance. Replace (2) faulty smoke detectors, system restored.