

NOTICE

**SCHOOL DISTRICT OF NEW GLARUS
BOARD OF EDUCATION
FACILITIES, TRANSPORTATION AND TECHNOLOGY COMMITTEE MEETING
MONDAY, JANUARY 8, 2018
HIGH SCHOOL CONFERENCE ROOM
6:45 PM**

AGENDA

- I. CALL MEETING TO ORDER - PAUL EICHELKRAUT**
- II. ELEMENTARY ROOF BIDS** 2
- III. ELEMENTARY FLOORING BIDS** 4
- IV. LONG-TERM FACILITIES PLANNING**
- V. ADJOURN**

POSTED :

NG HIGH SCHOOL
NG MIDDLE SCHOOL
NG ELEMENTARY SCHOOL
NG POST OFFICE
BANK OF NEW GLARUS
UB&T BANK OF NEW GLARUS
ANCHOR BANK OF NEW GLARUS

PURSUANT TO APPLICABLE LAW, NOTICE IS HEREBY GIVEN THAT A QUORUM OR A MAJORITY OF THE NEW GLARUS SCHOOL DISTRICT BOARD MEMBERS MAY ATTEND THIS MEETING. INFORMATION PRESENTED AT THIS MEETING MAY HELP FORM THE RATIONALE BEHIND FUTURE ACTIONS THAT MAY BE TAKEN BY THE NEW GLARUS SCHOOL DISTRICT BOARD.



Nations Roof North, P: 262-542-0002
 LLC F: 262-542-0003
 901 Sentry Dr.
 Waukesha, WI 53186

PROPOSAL- CONTRACT

PROPOSAL SUBMITTED TO:	Date: December 6, 2017	DESCRIPTION OF JOB:
New Glarus Elementary School		Job Name: New Glarus Elementary – Roof Replacement
		Job Address: 2 nd . St
		Job City: New Glarus, WI 53574
Attention: Larry McGowan	Fax: larry.mcgowan@ngsd.k12.wi.us	

Nations Roof is pleased to submit the following proposal for the above referenced site. Our proposal to supply all necessary labor & material for the scope of work and exclusions described below.

- Furnish and install a 24ga Prefinished Standing Seam Metal Roof, 18" o/c, with concealed fasteners and over 18ga x 1" inverted Hat Channels 24" o/c with 2" batten insulation between hats over the existing roof system. Includes all necessary trim and accessories. Color to be chosen from a Standard Pac-Clad color chart.

TOTAL PRICE - \$ 89,500.00

Voluntary Alternate – In lieu of the above mentioned system, furnish and install 1" Rigid Polyisocyanurate with high temp ice and water shield with bearing plates. – **Deduct \$2,200.00**

We Hereby Propose to furnish labor and materials complete in accordance with the above specifications, for the Sum of eighty-nine thousand five hundred dollars and no/100.

Exclusions:

- Sales Tax

Authorized
 Signature Tim Hitt

Note: This Proposal may be with-drawn by us if not accepted within 30 days.

Acceptance of Proposal

The above price, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outline herein.

Owner
 Signature _____

Date Accepted: _____

Print Name _____



CAPITAL
CITY SHEET METAL, INC.
4938 FEMRITE DRIVE

608-221-4420
MADISON, WI 53716

BID FAX TRANSMITTAL
Fax: 608-221-1031

To: New Glarus School District Attn: Larry McGowan

Fax No: _____ Date: 12/7/17

Please accept the following bid:

Project Name: New Glarus Elementary School

Location: 1420 2nd Street New Glarus, WI 53574

Section(s): Furnish and install 24 gauge prefinished steel standing seam roofing with all associated flashings and trims. Includes 1" rigid polystyrene insulation and 18 gauge Z furring.

Bid Amount: \$ \$101,740⁰⁰

Notes, Exclusions, etc. Standing seam roof panels to be equal to as specified. Manufactured by Capital City Sheet Metal
Per Plans dated 5/9/17

Addendums Recognized: -0 Submitted by: John T. Schluogh



New Glarus School District Elementary School: Polished Concrete Flooring

COMPANY | New Glarus School District
CONTACT | Larry McGowan – Director of Building & Grounds
PROJECT ADDRESS | 1420 2nd St. New Glarus, WI
PHONE NUMBER | 608.214.5975
FAX AND/OR EMAIL | larrymcgowan@ngsd.k12.wi.us
DATE | December 20th, 2017
PAGES | 2
PREPARED BY | Dmitry Brodsky 262.242.5757

SCOPE OF WORK

Polished Concrete (5,678 SF)

Install polished concrete flooring system using planetary grinders, diamond tooling and high-performance vacuum systems. Per manufacturer specification install Concrete Densifier and LS Guard – Stain guard. Includes standard Salt/Pepper finish and polish to a final sheen of 800 grit (Level 3 - Medium Sheen). Includes all hand-tooling along wall edges and doorways. Route/Clean and fill any unfilled control joints with QWIK Joint 200 polyurea joint filler.

Alternate 1: Highest Sheen

Additional mechanical polishing steps to create Level 4: 3000 grit (highest sheen) floor.

Alternate 2: Deep Grinding

Deep grinding will create large and more uniform aggregate exposure and finish. This process consists of using a vertical milling machine followed by removing the profile create by the milling machine using a planetary grinder and diamond tooling.

Alternate 3: Dye/Color (2,924 SF, Hallways Only)

Install one color Vivid Dye to entire hallway area.

Patching/Repair *Allownace, only if needed*

Pricing given as an allowance to be included only if needed based on time and materials.

CONDITION NOTES

Note: We will polish as close as possible to obstructions. All portable equipment removed and replaced by others. 480v 3-phase 50amp power, water, dumpster and sanitary sewer supplied by owner. Aggregate size may vary due to concrete pour. Some

preexisting conditions in the floor may be visible upon completion of restoration process. If small pitting exists after grinding the floor we can skim/grout coat the entire are and re-grind at an addition cost. Any heavy patching/repairs to be discussed and billed separately once approved. All pricing is based on installation in one mobilization.

ITEM	UNIT PRICE	QUANTITY	TOTAL COST
PC	3.85	5,678	21,860
Alternate 1: Highest Sheen	.40	5,678	2,271
Alternate 2: Deep Grinding	1.39	5,678	7,892
Alternate 3: Dye/Color	.49	2,924	1,433
Patching/Repair *Allowance*	xx	xx	1,250

Thank you for the opportunity to work on this project!

stain

no stain 33,273
no dumpster
no generator



Darren Pavlik . dwpavlik@coylecarpet.com
250 W. Bellline Highway . Madison, WI . 53713
P: 608.327.5130 . F: 608-258.7248 . C: 608-628-6361

PROJECT INFORMATION:

Project Name:	New Glarus School - Elementary Cafeteria		
Date:	Tuesday, December 12, 2017		
Project Address:	1420 2nd Street		
Customer Name:	New Glarus School District		
Contact Name:	Larry McGowen	Contact Phone:	608.214.5975

PROJECT NOTES:

- Concrete Polishing existing VCT floors.
- Removal and disposal of existing VCT is included
- New Vinyl base is included.
- All work figured during regular business hours.
- Vinyl Base Selection - Johnsonite 4" High Color TBD
- Power will need to be hooked up by electrician.

VCT Removal	\$1,900.00	} 17,750
Concrete Polishing - Materials and Installation	\$15,500.00	
Staining Concrete Option - Materials and Installation	\$2,100.00	
Vinyl Base - Materials and Installation	\$350.00	

stain

5

no stain
no dumpster
no generator

\$35,525⁰⁰



Darren Pavlik . dwpavlik@coylecarpet.com
250 W. Beltline Highway . Madison, WI . 53713
P: 608.327.5130 . F: 608-258.7248 . C: 608-628-6361

PROJECT INFORMATION:

Project Name:	New Glarus School - Elementary Hallways		
Date:	Tuesday, December 12, 2017		
Project Address:	1420 2nd Street		
Customer Name:	New Glarus School District		
Contact Name:	Larry McGowen	Contact Phone:	608.214.5975

PROJECT NOTES:

- Concrete Polishing existing VCT floors.
- Removal and disposal of existing VCT is included
- New Vinyl base is included.
- All work figured during regular business hours.
- Vinyl Base Selection - Johnsonite 4" High Color TBD
- Power will need to be hooked up by electrician.

VCT Removal	\$1,850.00	} 1775
Concrete Polishing - Materials and Installation	\$14,950.00	
Staining Concrete Option - Materials and Installation	\$2,050.00	
Vinyl Base - Materials and Installation	\$975.00	

stain →

COYLE CONTRACT PM: Darren Pavlik ACCEPTED BY: _____
NOTE: THIS PROPOSAL MAY BE WITHDRAWN IF NOT ACCEPTED WITHIN 30 DAYS



New Glarus Elementary School:

Larry McGowan
 1420 2nd Street
 New Glarus, WI
 (608) 214-5975
 Larry.mcgowan@ngsd.k12.wi.us

Q#111017-NGS-CS	Polished Concrete: 5,678 S.F.	November 10th, 2017
------------------------	--------------------------------------	---------------------------------------

Remove VCT

1. With Riding scrapper, mechanically scrape floor to remove VCT
2. With planetary grinder, mechanically scrape the concrete to remove adhesive
3. Hand grind all edges to remove adhesive

Polish Concrete

1. Start off with appropriate grit diamonds and mechanically grind the surface for a flat surface.
2. Fill control joints with polyurea joint filler.
3. Patch holes and cracks in concrete with structural urethane and polymer modified concrete
4. Once grinding is complete begin polishing at 100 grit.
5. Sequentially increase the grit level to 400 grit.
6. Seal the concrete with hardener and densifier system and allow to cure.
7. Once sealer has cured polish the concrete to 800 grit
8. Apply the stain guard system and burnish the concrete to 1500 grit.

Alternate 1 – Install Vinyl Base

A deduct is given not to mill the concrete to reach course aggregate. Milling the concrete can cause aggregate release and additional damage to the concrete that less aggressive grinding will not cause.

Project Notes:

- Prepping equipment runs on 480V, 3 phase, 50 amp power. An additional price is given if a generator is needed.
- Proposal does not include a dumpster. If Floorcare is required to provide a dumpster, additional costs would apply.
- Floorcare Cannot guarantee the color and consistency of aggregate exposed
- Floorcare to have exclusive access to area for the duration of the work.
- Concrete previously covered with VCT can have a permanent ghosting pattern.
- The condition of the concrete will play a major impact on the final polishing results

Base price:	\$43,924.00
Alternate 1 – Install Vinyl Base:	\$3,150.00
Additional price if a generator is needed:	\$1,950.00

Net 30 days; FCUSA reserves the right to invoice client for all materials & supplies upon proposal acceptance.
 If bid is accepted, please sign this form and fax to Floorcare USA, Inc. It is understood that there is no agreement without a signed copy of this proposal or a signed purchase order. Project quoted to be performed in one phase, wide open space unless otherwise agreed to.

Name: _____ Title: _____

Signature: _____ Date: _____


(Quote subject to the attached warranty and terms & conditions)

Floorcare USA Representative: Chris Schmidt
Phone: 262-786-0770 x113
Email: chris.schmidt@floorcare-usa.com

#49,024

New Glarus Elementary School:

Larry McGowan
1420 2nd Street
New Glarus, WI
(608) 214-5975
Larry.mcgowan@ngsd.k12.wi.us





PROJECT DETAILS:

Proposal includes all materials, freight, labor, tools, supplies, equipment, supervision, liability insurance, workers compensation insurance and is based on completing all work in it's entirety in one move-in, unless otherwise stated in the proposal; and Floorcare USA, Inc. (referred to as FCUSA) having uninterrupted work. Interruptions or interference, from any source, which cause delay in work, will result in a change order to compensate FCUSA for extra time and expenses incurred. This bid is subject to review after 60 days or if there is a substantial change in material cost, labor rates, or size of area to be installed. Proposal doesn't include (unless stated in scope): 1) Removal of tape, ink, mastic, or adhesives, paint overspray, existing sealers, coatings, or stains; 2) Removal of concrete spillage, splash or stains embedded in or on the surface; 3) Repair of cracks, joints, holes, divots, pitting or other surface defects. Products delivered to the job site shall be invoiced immediately if project is delayed. Such products may be subject to a restocking fee if job is canceled. Owner/GC/Lessee shall receive and provide a secure storage area for materials as they arrive and storage should be suitable for storing flammable and/or corrosive materials. Owner/GC/Lessee shall be required to provide information regarding structural or chemical conditions not necessarily apparent during pre-examination of the project such as: accelerators, curing chemicals, fibers in the concrete, silicone absorption, carbon/graphite or sulfur contamination or any other form of foreign or chemical contamination that might be in the concrete. FCUSA shall not be responsible for additional costs incurred from such conditions. Items that shall not be the responsibility of FCUSA which could result in additional costs include: 1) Roof or pipe leaks over wet coating; 2) Coating failure caused by cold temperatures or airborne dust resulting from imprudent acts of others; 3) Coating failure or staining caused by employees, forklifts or chemical spills; 4) Burning of concrete fibers, patching or crack repair unless specified in quote; 5) Fish-eye flaws due to silicone absorption present in the concrete; 6) Failure due to Moisture Vapor Pressure (MVP); 7) Any coating failure or coating performance defect due to moisture levels over 3-pounds; 8) Failure due to Alkalinity Silicate Reaction (ASR); 9) If Acid Etching is specified the concrete must be wet cured, removal of steel power troweled surface, curing compound, hard & seal, hardener, densifier, cure & seal, or any type of sealer system cannot be achieved through an acid etch. 10) Additional prep work to remove debris, stain, paint overspray, dry wall mud or any other residue or damage caused by other trades unless this removal is specified in the proposal. 11) Additional preparation or resurfacing required to adhere coatings if a high concentration of fly ash or other additives that impede the adhesion of flooring materials or any form of surface contamination not made known prior to starting. FCUSA will provide Material Safety Data Sheets (MSDS) prior to the start of the contract. Some coatings emit odors, which may be objectionable to others and it shall be the responsibility of the Owner/GC/Lessee to vacate the area or inform personnel of the hazardous concerns. FCUSA shall not be responsible for lost wages, lost production or lost profit or consequential damages resulting from any possible disruption of others.

JOB SITE CONDITIONS AND EXCLUSIONS:

Owner/GC/Lessee: 1) will provide a representative who shall have the authority to issue and approve changes in the project and render decisions promptly; 2) shall provide a dumpster for all non-hazardous debris related to the floor installation; 3) Will have the area free of all trades and traffic during, and 48 hours after flooring and/or coating installation. FCUSA shall not be responsible for damage caused by traffic during construction. If the floor and/or coating installation is damaged for any reason due to other trades there is an additional fee to re-apply the floor and/or coatings; 4) Shall have floors swept and clean prior to FCUSA arrival & free from paint, oil, grease, dry wall mud, chalk-lines, over-sprays and foreign residue caused by other contractors (other trades are responsible for cleaning up after themselves) 5) Is responsible for moving equipment or providing dust protection. If FCUSA has to wait on the Owner/GC/Lessee to move obstructions, the Owner/GC/Lessee will pay FCUSA at a rate of \$77.50 per man hour; 6) Is responsible for security of the facility/job site; 7) Is responsible for providing lights, water, electricity, heat and 24 hour access to the project site; 8) Is responsible for on site power requirements of 220 Volt, 50 Amp, 3-Phase or 480 Volt, 50 Amp, 3-Phase no farther than 200 feet from flooring area to be treated as well as 110 Single Phase. If FCUSA is required to bring in a generator, the generator will be billed at \$495.00 per 8 hours of run time, plus diesel fuel cost; 9) Will provide protection to equipment & unprotected metal surfaces. While all concrete prep equipment is equipped with industrial vacuum systems, mechanical surface preparation is never dust free; 10) The building to be coated should be kept at a controlled temperature (65-85 degrees Fahrenheit) fourteen (14) days prior to installation of the coating; 11) Sprinklers surrounding the perimeter of the building must be turned off prior to installation of any floor and remain off for two (2) days after the floor has been installed; 12) will inform the flooring contractor of any potential hazardous conditions (i.e. asbestos).

PROJECT SCHEDULE AND CANCELLATIONS:

FCUSA requires a minimum three-week lead time to schedule a project, based on the work load at the time a scheduling request is made, no guarantee's or commitments of time frames are made until a signed contract is received and the client speaks with a representative from FCUSA concerning the dates and times available. The Owner/GC/Lessee shall be responsible for "False Starts" which are defined as any instance when FCUSA has been notified to proceed with the contract but conditions do not allow for the work to proceed. "False Starts" are chargeable at a minimum rate of four hours per worker plus travel costs. Additional costs, such as restocking, transportation costs, etc. will also be the responsibility of the Owner/GC/Lessee. Should FCUSA not finish the contracted work in specified time for reasons due to the Owner/GC, an additional trip charge will be applied for extra man-hours & travel. Time frames for installation are estimates, FCUSA cannot be held responsible for unforeseen challenges identified within the project. Cancellation or rescheduling of the project once it has been scheduled by the client will result in a charge of 30% of the contract price, unless FCUSA can fill the time slot with other work. Cancellations will also incur a restocking charge if materials have been shipped to the job site or the office of FCUSA prior to cancellation. FCUSA is not responsible for unforeseen conditions including but not limited to rain, cold temperature, strong wind, blowing debris, hurricane, tornado, earthquake or any unforeseen conditions which cause delays, increased labor, or increased material costs; these are the responsibility of the owner, and will be charged as a change order.

SUBSTRATE SPECIFICATIONS:

The provided concrete is assumed to meet ACI 302.1 standards, is structurally sound, dry and contaminate free before application of the floor coating material, meet ICRI Guidelines and have a compressive strength of at least 3500psi and at least 200psi in tension. If the concrete to be coated has a soft or weak cap or is contaminated, these are considered an unforeseen condition, which cannot always be identified until shot blasting, diamond grinding or the coatings/flooring applications have been performed. When shot blasted or diamond grinded, concrete with a soft cap tends to have a much heavier profile and can require additional prepping and coating procedures. When shotblasted, diamond grinded or coating; a weak cap may require additional prepping and coating procedures. If a soft or weak cap is identified in all or part of the slab, the customer will have the option of applying more material or a resurfacer to the slab; for an additional cost. As well, shot blasting or diamond grinding can open up "cracks" that were not visible during the pre-job survey and will require a change order to fill. Failure to put this additional epoxy or resurfacing system on the floor will leave an aesthetically displeasing surface, for which FCUSA will not be responsible. Protection of flooring: No satisfactory chemical or cleaning procedure is available to remove petroleum stains, chemical stains or chemically etched stains from the concrete surface; especially when its newly curing concrete; stain/chemical prevention is essential. All hydraulic powered equipment must be diaphraged. Food, tobacco products, soda, liquids can all permanently alter the appearance of the concrete if spilled; especially on newer, freshly cured concrete. No trade will park on the slab or store materials/products. If necessary to complete their scope of work, drop clothes will be placed under vehicles at all times. No pipe cutting machine will be used on the inside slab. Steel will not be placed on the interior slab to avoid rust staining. Owner/GC/Lessee shall keep the floor dry and notify FCUSA if it has been exposed to water or moisture fifteen days (15) prior to the application date. Concrete moisture testing or core testing may be required. Relative Humidity Testing ASTM F2170 test results must meet 75% - 80% readings (Verify with manufacturer of each product). Calcium Chloride testing ASTM F1689 readings must be below 3 pounds per 1,000sqft feet on the calcium chloride test. Although testing is helpful, it is not a guarantee against future problems. This is especially true if there is no vapor barrier or the vapor barrier is not functioning properly and/or you suspect you may have concrete contamination from oils, chemical spills excessive salts or some other form of foreign contamination. This proposal does not include moisture testing or core testing unless otherwise agreed upon in the proposal. Testing for vapor emissions or core testing for forms of contamination is the customer's responsibility and is required (at customer's sole expense) for the Limited Warranty to apply. FCUSA can provide testing at an additional fee if requested. If moisture testing or core testing is completed from an outside source, test results are to be furnished to FCUSA no less than forty-eight (48) hours prior to install.

PAYMENT TERMS:

Net 15 days unless otherwise agreed upon and a 30% deposit required to schedule the project and the remaining due upon completion. If payment is not received within specified time frame, FCUSA reserves the right to charge 1.5% interest a month until payment in full. If there is a dispute concerning project quality, performance, color or any other irregularity with the project, the customer has the right to withhold a 5% retainer on the outstanding balance until an amicable conclusion is reached. FCUSA reserves the right to refrain addressing any concerns/issues with a project until a minimum payment of 95% of the outstanding balance has been received. In the unfortunate circumstance that a legal challenge is required to address an issue, all disputes will be settled in Waukesha County, Wisconsin or an alternate venue as designated by FCUSA. In the event FCUSA incurs any costs or expense of any nature in preparing for the prosecution of and prosecuting any claim against the Owner/GC/Lessee, whether by means of negotiations, arbitration or legal action, arising out of the Owner/GC/Lessee's refusal to pay for the work/materials provided by FCUSA, FCUSA shall be compensated for any such costs and expenses, including attorney's fees.

PRIME CONTRACTOR NOTICE OF LIEN RIGHTS:

As required by the Wisconsin construction lien law, contractor hereby notifies owner that persons/companies performing, furnishing, or procuring labor, services, materials, plans, or specifications for the construction on owner's land may have lien rights on owner's land and buildings if not paid. Those entitled to lien rights (in addition to the claimant) are those who contract directly with the owner or those who give the owner notice within 60 days after they first perform, furnish or procure labor, services, materials, plans, or specifications for the construction. Accordingly, owner probably will receive notices from those who perform, furnish, or procure labor, services, materials, plans, or specifications for the construction, and should give a copy of each notice received to the mortgage lender, if any. Claimant agrees to cooperate with the owner/owner's lender, if any, to see that all potential lien claimants are duly paid.



FLOORCARE USA, INC., OFFERS A (1) ONE-YEAR WARRANTY:

This flooring system is covered by a one-year warranty against adhesion failure due to poor workmanship or defective materials. This warranty guarantees that all installed products and systems will perform in exact accordance with manufacturers stated specifications and covers labor and materials only. Any and all remedies Owner may have against FCUSA for defects in workmanship are limited, as set forth in the Limited Warranty, and in no event shall FCUSA be liable to the owner for incidental or consequential damages, including, but not limited to: lost profits, business interruption expenses, and/or expenses incurred in moving and/or storing occupants, equipment, or inventory which might be affected by repair operations.

This warranty excludes adhesion failure or performance defects where the cause is: Moisture Vapor Transmission, Alkalinity Silicate Reaction (ASR), coatings failure where moisture levels are beyond 3-pounds, substrate failure, substrate contamination or abuse. FCUSA disclaims any liability for any defect or failure including: blistering, peeling, cracking or delaminating caused in whole or in part by: hydrostatic pressure, osmotic ground water pressure, vapor drive, hydration, or any other moisture/water related failure; ground movement or settling; structural or substrate failure; Un-reacted Metasilicate Contamination (UMC); cosmetic defects due to scraping, gouging, staining or discoloration; building alteration; improper design or construction of the substrate on which materials are applied; substrate contamination of any form; acts of God (hurricane, tornado, etc. . .) normal wear and tear and any cause beyond the control of FCUSA.

Moisture vapor transmission is the condition arising from the attempted permeation of moisture through the applied flooring system. The source of moisture can be from sub base or groundwater conditions below the substrate especially in the absence of a moisture barrier. It can also be present in new concrete installations that have not sufficiently cured. Whatever the source, the attempted escape of moisture through a barrier that is not moisture permeable (i.e. new flooring system) can cause significant delaminating, blistering or defects in the applied system. In cases where site tests indicate moisture (particularly in new construction) delays may be encountered while waiting for the concrete to dry sufficiently.

When you demand use of an area before the substrate is adequately dry, a written authorization will be required before any work begins. Substrate failure occurs when delaminating, spalling, or degradation of a concrete surface occurs as a result of poor workmanship or materials by the concrete contractor. Often such symptoms are evident before any finishes are applied, but certain conditions; i.e. "soft" or "powders" or "punky" concrete or aggregate pop-outs may only become evident after several months of steady traffic. Delaminating caused by abuse may occur when: personnel gouge the floor with nails protruding from skids, drop heavy objects, or pour paint remover on the floor. Excessive point loading of material carts is another cause of damage where the psi load on wheeled carts (particularly steel wheels) exceeds the design specifications of the applied system. High temperature activities such as welding are another source of abusive damage. If a significant change in use occurs (from warehouse space to a plating line, for example), this Warranty for wear is void unless the new use is accepted in writing by FCUSA. Certain conditions that affect wear also limit the Warranty coverage: abusive damage caused by personnel while relocating materials on the floor, dragging equipment, pushing skids or using inappropriate cleaning solvents is not covered by this Warranty.

A maintenance program is essential to ensure the useful life and wear of the flooring and daily sweeping/scrubbing of loose debris, soil and dirt is a fundamental issue; since the abrasive nature of organic soils will accelerate wear. A periodic wet cleaning to remove oil spills and other residues is suggested.

Floorcare USA reserves the right to void any and all warranty coverage if the client fails to adhere to a consistent maintenance program in accordance with the Floorcare USA standard Floor Cleaning and maintenance guide. This maintenance guide is provided upon request and can be found on our website at: www.floorcare-usa.com

Warranty coverage does not apply to any areas where the client requests that we coat an exterior area with interior materials: i.e. Home Garage coating system where the exterior lip receives the coating system application. Interior coating materials are designed specifically for interior applications and their performance cannot be predicted or guaranteed in exterior applications. Warranty coverage does apply to exterior areas if the material specified for the application is an exterior grade product.

Warranty coverage does not apply to marks or stains left due to tire plasticizer marks. Plasticizer marks, also known as ghost marks or paw prints, are permanent, blackish marks of a wheel tread impregnated onto the floor or coating. Plasticizers are chemicals used in the manufacture of rubber wheels and after the wheel sits, for even a few minutes, the plasticizer may chemically react with the floors. The plasticizer penetrates and forms a chemical bond with the floor or coating, which results in a mark that cannot be removed.

METAL EDGES:

Avoid the placement of cabinets/fixtures with sharp metal edges and avoid dragging these type of fixtures across your floors; especially if it's a glossy top coat. If the placement of fixtures with sharp metal edges is going to occur, make sure some form of protection is placed between the metal fixture and the floor; clear sheets of plexiglass are a terrific option.

WHEELED CHAIRS, CARTS, TABLES and FIXTURES:

Avoid metal or hard plastic wheels from constantly moving back and forth across your floors in the exact same spot as this may dull, damage or prematurely wear out your coated floors. If in an office type setting where a wheeled chair, cart or table will be moving back forth constantly over the same spot in the floor, the placement of a clear plexi floor protector that can be found at any office store is recommended. Soft white, non marking rubber wheels and casters are recommended and for all wheeled chairs, tables, carts or objects that will be continuously used on the floors. For chairs and fixtures that don't have wheels, soft rubber end cap glides are recommended on the underside of all chairs, tables and fixtures.

ADHESIVES & COVERINGS:

It is not recommended that you apply adhesives to your concrete flooring system unless the installed flooring system was specifically applied for this purpose. Adhesives can damage your floor and the mastic/glue like residue may require a harsh or caustic chemical to remove the residue that could possible damage your floor. Some tapes; even Painters tapes, contain acids or solvents in the adhesive than can etch or alter the appearance of your floor; if protecting your floor use a breathable system like EZ-Cover to help avoid differential cure in your concrete.

SLIP DISCLAIMER

FCUSA and the manufacturer of the chosen system recommend the use of high-traction aggregate in all coatings or flooring systems that may be exposed to wet, oily or greasy conditions. However, textured surfaces can still be slippery under certain conditions. Type of activity on the flooring surface, maintenance procedures and type of footwear may all be factors to consider when deciding on the degree of traction needed for a given area. FCUSA, the manufacturer or their sales agents will not be responsible for injury incurred in a slip and fall situation. It's the end users' responsibility to provide for their own safety & to determine the suitability of the coatings for their particular application.

DECORATIVE CONCRETE DISCLAIMER:

Decorative concrete systems are hand crafted and not pre-manufactured flooring, therefore every system installation is unique and will present its own set of installation variables. FCUSA does not guarantee the consistency, color, texture, color variations, or aggregate consistency of concrete polish, dye/stain systems. These systems may not be completely uniform throughout the surface, along edges, in corners or underneath objects; corners will likely appear different as prepping equipment is round and corners are square and color/aesthetic variations in corners should be expected. Similar to natural stone products, the final outcome of these systems are designed to and may give an assortment of colors, swirls, mottling effects, blemishes, and hairline cracks; natural and desired when choosing these types of hand crafted systems. If seeking a uniform look, decorative concrete is not the right flooring choice to fit your needs. However, if you seek a unique floor that is beautiful, durable and simple to maintain, decorative concrete is the right choice for your flooring needs. High and lows in the slab may cause areas of greater and lesser grind that can lead to variation in aggregate exposure and finish. All concrete will have a variation in finish and aggregate exposure. Even in new construction, aggregate exposure along the edges may not be consistent with the majority of the floor. Color variations, texture variations and mottling are normal aspects of a concrete dye/stained surface and cannot be predicted or guaranteed; especially on older floors. These variations give the floor character and showcase the natural beauty of the floor's complexion.

The finished floor is susceptible to staining, chip-outs or scratches if a heavy or sharp object is pulled across the floor. Cracks, chips and stains that are currently in the concrete may still be noticeable upon completion of the grinding/polishing process. On most floors there will be a densifier or a stain resist product used which will help protect the floor. These products will buy time to clean a spill. If spills are not cleaned in a timely manner the densifier or stain resistant product will not prevent stains. Some acidic products may stain or "etch" the surface instantly, depending on the level of acid in a product. The best prevention to staining is cleaning all spills in a timely manner. For staining, scratches, and chip-outs there are ways to help mask the problem, but there may not be means to remove the problem. Stains may be reground and polished, but if the stain penetrates deep into the concrete, it will remain after re-polishing. Depending on the size, scratches and chip-outs may be filled but will still be noticeable after completion. Topical dyes and acid stain coloration systems create custom translucent color effects, and are not designed to, and will not hide surface discoloration, blemishes, impressions, cracks, markings or other construction variables. Variables that occur during installation are due to each unique working environment (i.e. lighting, temperature, airflow, humidity, and, existing floor condition). Decorative concrete surfaces are striking in appearance and add to the artistic features of modern sculptures, floors, walls and accessories. If patching or troweling is required, these areas will offer a different appearance than the rest of the floor as the patching material accepts stain differently than the concrete or overlay and this is a normal aspect of this type of process.

Owner/GC/Lessee must take the necessary precautions to protect concrete surface from all construction damage after the installation of the floor and until final acceptance by the Owner. Protection should include the use of a breathable protection like EZ Cover or Ram Board and in areas that require overhead work, plywood or OSB chip board should be placed on top of the paper for additional protection. Site foreman should pay close attention to the protection during construction and repair any rips or tears. To prevent stains and spills, do not allow food or drinks into space during the duration of the project. Do not apply duct tape or any other tape/adhesives directly onto the floors. All onsite trades should be notified that the concrete floor in place is the finished floor. Follow all maintenance instructions and care procedures as it is essential that the floor be kept clean as dirt and other contaminants on a polished/decorative concrete floor will act as sandpaper and will diminish the its appearance. The total system design must be considered to ensure safe, long lasting, trouble free performance. FCUSA does not take responsibility to determine and/or specify systems as stated above as the function, material compatibility, adequate physical characteristics, and maintenance, are the responsibility of the selected architect, designer and ultimately the end user/owner.

Floorcare USA Inc. • 2246 W. Bluemound Road., Suite A1 • Waukesha, WI 53186

Phone: 262-786-0770 • Fax: 262-786-5284

www.floorcare-usa.com • Member of the BBB-Better Business Bureau