

Board Report 11/10/25

All pumps and sprinkler systems are blown out.

Idaho Power dropped a leg of power at the middle school, we lost a motor on the kitchen hood, a HVAC board on a furnace and some electrical on the steam kettle.

Bussing as normal, still short subs but able to make it all work.

The roof on the old gym needs coated, the membrane is rotted and worn.

Dan Aberasturi.