



**ROOF PROGRESS REPORT: *Final* 06-20-2025**

<b>Contact:</b>	Ryan Palmer (507) 402-6783 <a href="mailto:rpalmer@tremcoinc.com">rpalmer@tremcoinc.com</a>
<b>Inspector:</b>	Kevin Johnson (763) 458-0272 <a href="mailto:kjohnson@tremcoinc.com">kjohnson@tremcoinc.com</a>
<b>Contractor:</b>	Western Specialty Contractors
<b>Project Manager:</b>	David Grandbois (612) 685-7107 <a href="mailto:davidlg@westernspecialtycontractors.com">davidlg@westernspecialtycontractors.com</a>
<b>Foreman:</b>	Larry Hadley (612) 860-9347 <a href="mailto:larryh@westernspecialtycontractors.com">larryh@westernspecialtycontractors.com</a>


**Crew has completed all façade work**


Through Wall Flashing Complete **Light Green**  
Through Wall Flashing Complete **Blue**  
Through Wall Flashing Complete **Pink**  
Precast Sealant Replacement & Penetrating Sealer Complete  
**Red & Orange**  
Through Wall Flashing Complete **Yellow**  
Through Wall Flashing Complete **Green**

**Issues and Corrections**

N/A

**Project Map:**



-  Current Area of Work
-  Areas Completed

## ROOF PROGRESS REPORT: *Final 06-20-2025*



Through Wall Flashing Installation in progress above windows. Window Protection  
Noted (Green Area)



## ROOF PROGRESS REPORT: *Final 06-20-2025*



Flash by end dams at the brick are under the condensate line due to mechanical line  
(Green Area)



## ROOF PROGRESS REPORT: *Final 06-20-2025*



Through Wall Flashing Installation in Progress above windows (Green Area)



## ROOF PROGRESS REPORT: *Final 06-20-2025*



Completed Through Wall Flashing Installation (Green Area)



## ROOF PROGRESS REPORT: *Final 06-20-2025*



Completed Through Wall Flashing (Green Area)



## ROOF PROGRESS REPORT: *Final* 06-20-2025



Completed Through Wall Flashing (Green Area)



## ROOF PROGRESS REPORT: *Final 06-20-2025*



Completed Through Wall Flashing  
(Green Area)