


**JOHN S. GRAVES & ASSOCIATES, INC.**  
**ARCHITECTS**

202 HORNBY PLACE  
UVALDE, TEXAS 78801

Phone (830) 278-6677  
Fax (830) 278-6679



**ARCHITECT'S  
FIELD REPORT**

OWNER   
ARCHITECT   
CONSULTANT   
FIELD



**PROJECT:** NEW CONCESSION BUILDING & TRACK RENOVATIONS FOR BRACKETT I S D  
BRACKETT VILLE, TEXAS  
**CONTRACTOR:** PIONEER CONCEPTS, LP  
**OWNER:** BRACKETT I S D

**DATE:** 10/24/06

**TIME:** 3:00 PM

**PRESENT AT SITE:** JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC  
MIKE BIZZEL - PIONEER CONCEPTS, LP

- 1 Steel set for foundation and ready to pour
- 2 Clean out loose dirt in trenches
- 3 Tape poly at plumbing pipes
- 4 Sidewalk and drainage flow to be checked

REPORT BY: \_\_\_\_\_

A handwritten signature in black ink, appearing to read "John S. Graves, Jr.".

John S. Graves, Jr.

**JOHN S. GRAVES & ASSOCIATES, INC.**  
**ARCHITECTS**

202 HORNBY PLACE  
UVALDE, TEXAS 78801

Phone (830) 278-6677  
Fax (830) 278-6679

**ARCHITECT'S  
FIELD REPORT**

OWNER   
ARCHITECT   
CONSULTANT   
FIELD

**PROJECT:** NEW CONCESSION BUILDING & TRACK RENOVATIONS FOR BRACKETT I S D  
BRACKETT I VILLE, TEXAS  
**CONTRACTOR:** PIONEER CONCEPTS, LP  
**OWNER:** BRACKETT I S D

DATE: 11/02/06

TIME: 2:30 PM

PRESENT AT SITE: JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC.  
MIKE BIZZEL - PIONEER CONCEPTS, LP

1. Masonry work started. Mortar color looks good wet, but too white when dry. Make darker when dry.
2. Water to run overhead. Furnish price on 10 gallon water heater and ~~install~~ water heater unit.

*INSTALL*



REPORT BY: \_\_\_\_\_

A handwritten signature in black ink, appearing to read "John S. Graves, Jr.", written over a horizontal line.

John S. Graves, Jr

**JOHN S. GRAVES & ASSOCIATES, INC.**  
**ARCHITECTS**

202 HORNBY PLACE  
UVALDE, TEXAS 78801

Phone (830) 278-6677  
Fax (830) 278-6679

**ARCHITECT'S  
FIELD REPORT**

OWNER [ ]  
ARCHITECT [X]  
CONSULTANT [ ]  
FIELD [ ]

**PROJECT:** NEW CONCESSION BUILDING & TRACK RENOVATIONS FOR BRACKETT I.S.D  
BRACKETT VILLE, TEXAS  
**CONTRACTOR:** PIONEER CONCEPTS, LP  
**OWNER:** BRACKETT I.S.D.

DATE: 11/08/06

TIME: 3:30 PM

PRESENT AT SITE: JOHN S. GRAVES, JR. - JOHN S. GRAVES & ASSOCIATES, INC.  
MIKE BIZZEL - PIONEER CONCEPTS, LP

1. CMU walls almost complete. Mortar color looks good.
2. Plumbing / Electrical being installed in walls.



REPORT BY: \_\_\_\_\_

A handwritten signature in black ink, appearing to read "John S. Graves, Jr.", written over a horizontal line.


John S. Graves, Jr.

**JOHN S. GRAVES & ASSOCIATES, INC.**  
**ARCHITECTS**

202 HORNBY PLACE  
UVALDE, TEXAS 78801

Phone (830) 278-6677  
Fax (830) 278-6679

**ARCHITECT'S  
FIELD REPORT**



OWNER   
ARCHITECT   
CONSULTANT   
FIELD

**PROJECT:** TRACK RENOVATIONS FOR BRACKETT I S D.  
BRACKETTVILLE, TEXAS  
**CONTRACTOR:** VIBRA-WHIRL LTD  
**OWNER:** BRACKETT I S D

DATE: 10/24/06

TIME: 3:00 PM

PRESENT AT SITE: JOHN S. GRAVES, JR - JOHN S. GRAVES & ASSOCIATES, INC  
RICHARD GORDON - VIBRA-WHIRL SPORTS LTD.

- 1 Interior grading of fields being completed.
- 2 Level topsoil at curbs approximately 3" below curb.
- 3 Location for high jump looks okay.
- 4 Contractor working on pole vault area.
- 5 Sprinkler contractor to furnish price on installing booster pumps.



REPORT BY:   
John S Graves, Jr