## **WOLF CREEK FACILITY ANALYSIS**

Facility Items that are wise, prudent and inevitable s	oon
Replace Roofs	\$75,000
Upgrade Playground	\$36,000
Replace Exterior Doors	\$16,000
Security Measures	\$5,000
Repaint Exterior	\$51,000
	\$183,000
Parille have that are vice and an artistic testing	A a service a
Facility Items that are wise, prudent and inevitable a	
Remove and replace old steam boiler	\$185,000
Refurbish worn out plumbing	\$22,000
ADA code upgrades	\$37,620
	\$244,620
Facility Items to offer similar quality as Manzanita	
All of the above	\$427,620
Retrofit Lighting	\$51,000
Retrofit Electrical	\$43,000
Refurbish gym floor	\$12,000
Refurbish lower playing field	\$18,000
Trotalblott lewel playing held	\$551,620
	7001,020
Facility Items needed for long term occupancy	·
All of the above	\$551,620
Remove Firtex	\$95,000
Remove Asbestos flooring	\$78,000
Refurbish restrooms	\$46,000
Replace siding	\$82,000
	\$852,620
Full suggested maintanense	
Full suggested maintanence	φο <b>τ</b> ο coo
All of the above	\$852,620
Re-design kitchen	\$31,000
Refurbish locker room	\$9,000
Paint Interior	\$36,000
Curb Appeal	\$26,500
Re-asphalt parking and playground	\$27,000
	\$982,120