

Technology Update

10/16/24

This week, the IT Dept asked administrators and directors to share any technology issues that need to be addressed or are outstanding.

Pioneer

Nothing new reported to IT Director

Oakwood

Projectors were installed in rooms 22 and 24. Electrician ran power yesterday.
The sound system in rooms 21, 22, and 24.

PJH

TV in 3 room dropping. IT can't replicate the problem when in the classroom. Techer requested a projector. The camera was pulled over to the new network and is online. Need to install Vape Sensors.
(Internet issues reported to the trustee were not reported to IT. When IT was informed, the problem was immediately fixed by reending the cable.)

PHS

PA system. All speakers in place. After centralizing room 223 tomorrow, then PA will work.

New gym centralization. Should be done next week.

FCHS

No new report

Construction Update

10/16/24

Elementary Pods

ADA ramp poured on outside doors to new rooms

The electrician will button up the panel / Wall tiles will be finalized / Tech???

Track

4" metal water main pipe 5' under track spang leak.

Pulled old out, put in new, and added additional conduit for future needs if needed.

(had previously added some conduit at the finish line)

Junior High

Sprinkler water main under three valves – brown grass under JH had the water turned off. Complete.

Entryway Man Trap – Door not lock. Maintenance will look into it

High School Fields

Field Markings/ cleaning up after games