

Buffalo-Hanover-Montrose Schools
 Radon Testing Summary
 As of 6/18/2014

Building	Date	Results of Test	Follow-up Action Required	Follow-up Performed	Date of Follow-up	Results of Follow-up	Further Action
PES	November-10	<= 4 PCL	Periodic retest 5 years				Retest after remodel
HES	May-12	>= 4 PCL	HVAC modifications	Retest	2012-13 and 2013-14 school year	<= 4PCL	Continue current HVAC settings- Periodic retest 5 years
MES	November to May 2014	<= 4 PCL	Periodic retest 5 years				
TES	November to May 2013	<= 4 PCL	Periodic retest 5 years				
DES	November-10	>= 4 PCL	HVAC modifications	Retest	January to February 2011	<= 4PCL	Periodic retest 5 years
NES	November to May 2014	<= 4 PCL	Periodic retest 5 years				
BCMS	November-10	<= 4 PCL	Periodic retest 5 years				
PHX	November to May 2014	<= 4 PCL	Periodic retest 5 years				
BHS	Not tested						Test 2014-15