

South San Antonio ISD Softball Facilities

2017-18

Proposed recommendations

- \$3,792.48 Foul territory to fence from dugout to outfield – convert from 4 to 6 ft.
- 500.00 Outfield warning track – red dirt
- 400.00 Air conditioning in press box
- 919.92 Fence crown protective guard
- 5,270.21 Enclose back warm-up area behind outfield fence 6 ft.
- 10,000.00 Leveling of field – top dress & sand
- No cost Remove partial wall of backstop for viewing purposes
- No cost Dugouts – ventilation

\$20,882.61 TOTAL

South San Antonio ISD
Softball facilities
2017-18
Parent requests

- \$ 574.57 Air conditioning for ticket booth, new door and 2 windows
 - 3,792.48 Foul territory fence from dugout to outfield-convert from 4 to 6 ft.
 - 500.00 Outfield warning track – red dirt
 - 23,468.00 Scoreboard
 - 12,800.00 Field lights- upgrade voltage
 - 13,000.00 Dugouts- extension of 6'
 - 919.92 Fence crown protective guard
 - 19,516.80 Additional batting cage
 - 400.00 Air conditioning in press box
 - 2,590.00 Sound system
 - 70,950.00 Elevated platform for bleachers – ramps, stairs, front walkway
 - 18,895.00 Canopies for home & visitor bleachers
 - 5,270.21 Enclose back warm-up area behind outfield fence
 - 4,399.96 Outfield windscreen – Chroma Bond w/imprint
 - 10,000.00 Level infield/outfield
 - 2,520.06 Storage shed (11'x14')
- \$189,597.00 TOTAL