



Cabinets have been put in the kitchen.




Bathroom tile has been placed in both bathrooms upstairs.



Flooring has been completed in Mr. Ansari's office (right) and Board Room (far end). As you can see, they are still working on getting the floor completed.



This is the ceiling of the reception area.



Pictured here is the south side of the building.

To the right are the cubicles and to the left are business offices.



This is one of the business offices. We will have 8 offices located on the east side of the building.



Pictured here is the north side of the building.

On the west side of the building, will be 8 cubicles that are slightly smaller than the business offices.



Here is the main entrance to the building.



Pictured is the exterior of the building completed with stucco and stone. The small windows face the cubicle areas.