

Transportation/Maintenance
Board Report

The new heating controls at the Elementary have sensors on them, so when the rooms are empty the thermostat goes in idle mode.

We are repairing a section of the high school roof that was damaged last winter.

Tom Muir