

From: Davis Smelley <[smelleydavis@yahoo.com](mailto:smelleydavis@yahoo.com)>

Date: Thu, Apr 10, 2025 at 9:18 PM

Subject: Mike S. Smelley bid

To: Mike Harper <[Harpermike@harletonisd.net](mailto:Harpermike@harletonisd.net)>

Mike S. Smelley  
2889 Mack Smelley Dr.  
Longview tx 75605  
903-738-1564

This is a bid to fix an existing erosion wash and add new parking in the baseball complex in the northeast corner of the facility.

Scope of work:

Mobilization

Prepare existing ditch and get ready for new pipe installation.

Install 150' of 24" pipe.

Import clay dirt to fill up ditch on top of pipe.

Lay geo fabric and install rip rap.

West side (by asphalt)

Fix topsoil and drainage buy the steps and slope.

Install 200' of 6" curb along existing concrete flume.

Shape up the existing rock/dirt parking and prepare for geo fabric and lay 6" of SB2 base on top (approximately 13,000 square feet).

East side parking

Strip grass and shape up using the dirt that is there prepare for geo fabric and install 6" of SB2 base (approximately 22,000 square feet).

Fix slope between batting cage and softball Feild and lay the two 6" pipes down to the main ditch.

Dress up slopes and fix washes around the two fields that we addressed.

Hydro mulch slopes and disturbed area (approximately 1 acre).

Total bid price \$265,000

This bid price doesn't include temporary piping for irrigation for grass.

This bid doesn't include soil cement for the (east) parking as mentioned to be an option if that is desired it would be an additional \$55,000.

Our approximate start date weather dependent is May 26 2025.