

Harvey Public Schools
Department of Buildings & Grounds
Mr. Kreatha Lewis

Buildings & Grounds Service Report

The following is an updated progress and scheduled service report from the department of buildings and grounds.

- **Brooks School**
 - a. Repaired multiple locks, doors and cabinets
 - b. Camera system assessment initiated
- **Holmes School**
 - a. Multiple Boiler and heat related problems resolved
 - b. Plumbing issues in crawl spaces repaired
 - c. Installed window blinds
- **Bryant School**
 - a. Repairs made on water valves in boiler room
 - b. Wall pack lights repaired
 - c. Initiate perimeter debris clean up
 - d. Installed window blinds
- **Sandburg School**
 - a. Major plumbing issues to boilers repaired
 - b. Assessment of camera system initiated
 - c. Compressor drain repairs initiated
 - d. New traffic signs ordered
- **Riley School**
 - a. Install vertical blinds in all c.o. offices
 - b. Repaired conference room heater
 - c. Repaired Malfunction in Metasys control
 - d. Diaphragm replaced in boiler room actuator
 - e. Univents repaired
 - f. Assessment of camera system
 - g. Clean debris and leaves from perimeter and play area
- **Angelou School**
 - a. Re-asses cost for P.A. Upgrade and repairs
 - b. Repairs to fire alarm system completed
 - c. Additional outlets installed in multiple classrooms
- **Lowell School**
 - a. Lights in boiler room repaired
 - b. Assessment of camera system
 - c. Initiate cleaning of storage rooms
 - d. Repair lights on stage

- a. Assessment of camera system
 - b. Clean perimeter of debris
 - c. Installed window blinds
- **C.L.A.S.S. School**
 - a. Kitchen area ceiling repairs in process
- **Notes**
 - b. Purchase of lawn equipment completed delivery in process
 - c. Entertain bids for camera upgrades
 - d. Formulating plan for parking problems at schools during arrival and dismissal times