3142 SCHOOL TRANSPORTATION SERVICES ALONG PRIVATE ROADWAYS

The Duluth Public Schools will provide transportation for eligible students living along township, road association, and private roadways if all of the following conditions are met.

- 1. The distance between the residence driveway and the main road or nearest serviced turnaround must be one half mile or more.
- 2. The roadway meets the following construction standards. The specifications are 18 foot finished driving surface. Surface of roadway must be at least 6" aggregate surface. All culverts across the roadway shall be 15" minimum diameter or larger.
- 3. The roadway is free of permanent, seasonal, or temporary safety hazards such as: unplowed roadway or turnaround, running water across roadway, tree branches or limbs in the way, steep shoulders with no guard rails, or any other possible safety compromising situations.
- 4. Adequate bus turnaround facilities are to be properly maintained. Turnaround facilities must be a minimum of 18 feet wide and 30 feet deep of finished surface without a serve grade in either direction. If a cul-de-sac is needed, it shall have a minimum 40 foot radius.

Roadways that do not meet the specifications of this policy and are receiving service as of September 9, 2004 will continue to receive service until such time that no students are eligible for service on the roadway. At such time service is requested to resume the roadway will be evaluated using the specifications described herein.

Applications for request for school bus transportation along roadways may be obtained from the ISD #709 Transportation Department. Roadways must be inspected and certified that they meet the above specifications by a licensed engineering firm. Costs of inspection and certification are to be borne by the applicant.

Final approval and acceptance will be made by the Duluth Public School Transportation Safety Committee.

The Manager of Transportation may suspend transportation services along an approvedroadway due to seasonal or temporary impassability, lack of adequate bus turn aroundfacilities, inadequate roadway maintenance, road construction, or the existence of a hazardous safety condition.

Adopted: 05-20-1997 ISD 709

Revised: 02-20-2001

09-21-2004 ISD 709