



November 9, 2021

**VIA EMAIL: Terry Felderhoff <felderhofft@eraisd.net>**  
**RE: Hornet Stadium Synthetic Running Track Resurfacing**

Good afternoon Mr. Felderhoff,

As you know, Hellas Construction, Inc. is working on the removal of the existing track surface at Hornet Stadium. We are seeing preliminary signs of some asphalt issues that may require some remediation. In an effort to remain proactive and avoid any delays once the inspection is complete, we would like to propose an allowance for asphalt repairs.

**Proposed Allowance**

If used, the allowance funds would be used to do the following:

1. Patch low areas on the track asphalt using polyurethane materials that are compatible with the track surface that is scheduled to be installed. These areas will be patched and leveled to match the required planarity.
2. Grind down high areas of the track asphalt all around track until these meet planarity requirements.

***We estimate this could cost up to \$40,000.00.***

**ALLOWANCE: \$ 40,000**

*NOTE: Allowance funds will only be used after your approval, through a zero-cost change order.*

Please review and let us know if there are any questions. Our office telephone number is (512) 250-2910. If this meets your approval, please sign and return this written approval to us. We look forward to hearing from you soon!

Respectfully,

APPROVED:

David Garcia  
Project Manager - Track Department

\_\_\_\_\_  
Authorized Signature

12000 West Parmer Lane

Austin, Texas 78613




Phone (512) 250-2910

Fax (512) 250-1960

info@hellasconstruction.com

[WWW.HELLASCONSTRUCTION.COM](http://WWW.HELLASCONSTRUCTION.COM)

**Exhibit A: Asphalt Inspection Report**



12000 West Parmer Lane

Austin, Texas 78613



Phone (512) 250-2910

Fax (512) 250-1960

info@hellasconstruction.com