Board Report for May 18, 2015

MAINTENANCE:

Been very busy. Falling a little behind on work orders. Been dealing with roof leaks. We have just two leaks left that didn't get fixed in the board room. Hopefully by board meeting it will be fixed.

TRANSPORTATION:

BB-2 is down because of the hydraulic pump is out. Hopefully at the meeting I will be able to give you an update. The A/C on BB-1, the clutch went bad on the compressor and waiting on parts on it. Hopefully it will be fixed before the board meeting. Other than that everything else is running great.

Chad Ely

Maint./Trans. Director

Sunray ISD