## CERTIFICATE OF APPROVAL FOR A TEN YEAR SURVEY REPORT

(Section 2-3.12 of the School Code)

OAKDALE ELEM SCHOOL	McLean					
School Building	County					
McLean County USD 5, 0050						
District Name	e and Number					

I, , State Superintendent of Education, acknowledge receipt of this ten-year safety survey report, approved for the year <b>0</b> .
Hence, the next safety survey report will be due in the year 0. The District architect has provided assurances that the building named above has been
surveyed in accordance with 105 ILCS 5/2-3.12. This Certificate of Approval for a Ten Year survey Report does not necessarily imply that Fire
Prevention and Safety Funds can be used for the work items listed in this survey report.

Date	Signature of State Superintendent of Education

### **COMMENTS:**

ITEM ID	DESCRIPTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	DIFFERENCE	REASON
---------	-------------	------------------	-----------------	------------	--------

## OTHER COMMENTS:

ITEM ID DESCRIPTION REASON	
----------------------------	--

(35-22) (7/07) Prescribed for ISBE for ISBE Use

# CERTIFICATE OF APPROVAL FOR THE EXPENDITURE OF FIRE PREVENTION AND SAFETY FUNDS

(Section 17-2.11 of the School Code)

	OAKDALE ELEM SCHOOL McLean										
	School B	uilding		C	ounty						
			M-1 O								
McLean County USD 5, 0050  District Name and Number											
	Amendment Number 25										
T											
	iously Approved	dmont #0.750.00									
<u> </u>	to raise with this Amenoved to Date										
	istrict Funds Approved	\$3,756.00 \$0.00									
		l .									
I, , State Sup	erintendent of Education, a	cknowledge receipt	of the estimate of	of cost certified by the architect/engir	neer required:						
				ety standards set forth in 23 III. as promulgated by the State Bo		5, 23 III.					
	bring the school buildir			estos Abatement Act 105 ILCS amended (AHERA).	105/1 et.seq, and t	he federal					
				ssibility; school security; repair							
3. playgrounds, parking lots, or school bus turnarounds; and other repair purposes pursuant to Section 17-2.11 of the School Code with funds not necessary for the completion of items under No. 1 or No. 2 above.											
I Further certify that the estimate of total approval to date, in the amount of \$3,756.00 has been examined and determined to be reasonable and is hereby approved.											
Date		Si	gnature of Stat	e Superintendent of Education							
EXPLANATO	DRY NOTES:										
1. 🗸 No	items in this amendme	ent were disappr	oved nor were	any of the estimated costs adj	usted.						
				and the estimated costs adjus							
				ndment reflects an aggregate c ems disapproved and cost adju							
	s certificate.			and sociality							
COMMENTS	<u>:</u>										
ADJUSTED	ITEMS:										
ITEM ID	DESCRIPTION	ESTIMATED AN	MOUNT	ADJUSTED AMOUNT	DIFFERENCE	REASON					

# APPLICATION FOR APPROVAL OF TEN-YEAR SAFETY SURVEY REPORT

(23 IL. Adm. Code Part 180, Sections. 180.310, 180.320, 180.330, 180.340)

NAME OF SCHOOL BUILDING OAKDALE ELEM SCHOOL	SURVEY YEAR 2026
NAME AND NUMBER OF SCHOOL DISTRICT McLean County USD 5, 0050	COUNTY McLean
ARCHITECT NAME Randall Middleton	FIRM MIDDLETON ASSOCIATES INC.
FIRM ADDRESS 1702 W. COLLEGE AVE, NORMAL, IL 61761-3028	TELEPHONE NUMBER (309) 452-1271

I certify that the survey referred to herein was prepared by me and to the best of my knowledge is a true and accurate.

and the same of th	Building in Full Compliance.	Commence of the control of the contr
	Building Not in Compliance	1 1 1 011 11 1 1 1 1 1 1 1 1 1 1 1 1 1
3/10/2025 Date	Randall Middleton  Printed Name Architect/Engineer	Medal Middle 001-007938 RANDALL E. MIDDLETON
Date	President of Board of Education	
Date 11/30/2026	Secretary of Board of Education 001-007938	
Expiration Date	License Number	[Seal and Signature]

Failure to submit accurate and complete safety survey reports as required shall subject a school district to the recognition provisions of 23 Illinois Administrative Code 180.

Form 35-86 (7/07) (Prescribed by ISBE for local board use)

180.300 a

# REQUEST FOR AUTHORIZATION To use Fire Prevention and Safety Funds

#### PART I. CERTIFICATION OF ESTIMATED COSTS

#### This is to certify that:

The <u>OAKDALE ELEM SCHOOL</u> school, located at <u>601 \$ Adelaide St Normal</u>, Illinois, and under the management and control of the Board of Education of School District # <u>0050</u>, <u>McLean</u> County, was surveyed by me on <u>3/10/2025</u>.

All of the urgent or necessary work as indicated on the attached Form 35-48 is necessary to abate the violations of applicable code requirements and should result in effecting compliance with said requirements within prescribed timelines. No violations of applicable code requirements other than those cited in previously approved safety survey reports or amendments and those noted in this survey or amendment were noted.

All other work recommended in the attached Form 35-48, though not required to abate violations of applicable requirements of the Health/Life Safety Code for Public Schools, is recommended for energy conservation; disabled accessibility; school security; repair of school sidewalks, playgrounds, parking lots, or school bus turnarounds; and other repair purposes provided in Section 17 2.11 of the School Code.

The certified estimated cost figures were prepared by me and to the best of my knowledge are true and accurate estimates of the costs to execute the work as specified. The total estimated costs to finance the work involved is \$ 3,756.00.

Name of Architect/Engineer Randall Middleton	Name of Firm MIDDLETON ASSOCIATES INC.	THE OF LETTING
Phone Number (309) 452-1271	Fax Number (309) 454-8049.	S. O.
License Number 001-007938	Expiration Date 11/39/2026	RANDALL E.
Email Address rand@middletonassociates.net	Melenthelelle	MIDDLETON
	[Seal and Signatule]	THE COLORS OF STREET

#### PART II. CERTIFICATION OF NEED (Provided by district through IWAS)

The local Board of Education hereby certifies and assures the State Board of Education:

- a. Based upon the report of the architect referred to above, the district faces total estimated costs of \$ to finance the work involved.
- b. The district has \$ available in its operations and maintenance fund, fire prevention and safety fund, school facility occupation tax fund and/or other fund to finance the work.
- c. If Fire Prevention and Safety funds are to be used, the district certifies that it has levied the maximum authorized rate for its operations and maintenance fund for the most recent year for which tax rates are available.
- d. The district needs to raise \$ in additional revenue through the levy of the Fire Prevention and Safety Tax or issuance of Bonds to finance the recommended work.
- e. Plans and specifications for the work will be submitted to the Regional Superintendent for review and approval.
- f. The work to be financed with Fire Prevention and Safety funds will not commence until the Certificate of Approval of the State Superintendent is received, the detailed plans and specifications have been approved by the regional superintendent and the regional superintendent (or other lawful agency) has issued an appropriate Order to Effect Compliance with the Health/Life Safety Code for public schools (or other lawful order requiring the work to be done).
- g. All work authorized by the District will be executed in conformity with all applicable codes.
- h. In the case of work recommended to repair school sidewalks, playgrounds, parking lots, or school bus turnarounds the notice and hearing requirements of Section 17-2.11 of the School Code were complied with by publishing the required notice on and holding the required public hearing on .

# VIOLATION AND RECOMMENDATION SCHEDULE (23 IL Adm. Code 180, Sections 180.320)

				TRICT CODE/NAME  3. FACILITY CO McLean County USD 5  OAKDALE ELE			
4. Item ID		,	7. Rule Violated	8. Description of the violation		9. Recommendation to correct violation	
1	Corridor 5	b.		Drinking Fountain is inoperartive. See also Illinois Plumbing CoolLCS 77 Section 890A Table B.	de 225	Remove the inoperative unit. Install new drinking foutain or repair existing drinking fountain.	
2	Entry 9	b.	1285 510 21	Electrical conduit to consul Heat Pump has been pulled apart or exposing wiring.		Repair conduit or install new metal conduit to this Heat Pump.	
3	Electric Room 111C	c.	185.50b)	Access to 400amp Main Distriburtion Panel is blocked by stored See also 185.510a). NFPA 70 requires that 10 ft in front of MDP not obstructed.		Clear out access to panel	

Form 35-84 (7/07) (Prescribed by ISBE for local board use)

## SCHEDULE OF RECOMMENDED WORK ITEMS AND ESTIMATED COSTS

1. COUNTY CODE 2. DISTRICT CODE/NAME 064, McLean 0050, McLean County USD 5						3. FACILITY CODE/NAME OAKDALE ELEM SCHOOL					
4. Item I.D.		6. Priority Code	7. Specification(s)	8. Units Of Measure	9. Quantity	10. Labor Code	11. Estimated Cost (Architect / Engineer)	12. ROE Adjustment	13. ISBE Adjustment	14. Estimated Completion Date	15. Funding Type
1	f	b.	New drinking fountain should meet current State of Illinois Accessability Code if possible.	unit	1	2	\$2,800.00			8/15/2026	F
2	е	b.	Peovide covering or protection for the wiring to the Heat Pump.	unit	1	2	\$280.00			1/15/2026	F
3	b	c.	Excess srtored material needs to be relocated.	unit	1	2	\$50.00			1/15/2026	F
										1	
						Subtotal	\$3,130.00	Adjusted Subtotal	\$3,130.00		
						Original 10.00%	<b>*</b> 0.40.00	Adjusted	004000		

Items with a Funding Type of 'O' are not included in the cost calculation. 35-48 (7/07) (Prescribed by ISBE for Local Board Use)