

Northland Community Schools

Independent School District #118



School Board Report

Date: Jan25

- AHU 2 air handler return motor failed – parts on order
- Main water heater repair completed – budgeting for new LTFM fund? to consider for business manager list
- MNPCA limited site investigation soil and vapor borings completed for tank spill Edwards Oil commissioned– report to follow with actions from State PM, Vendors quoted are Petrofund approved
- MAU for kitchen gas valve on order, lockout issues continue, venting repiped
- Chiller loop leak repair complete in lounge
- DHW pump circulation failed / replaced with SST per code
- Camera and duct detector issues for fire/ /smoke repaired