

Northland Community Schools

Independent School District #118

School Board Report

Date: Feb25



- Main west sanitary waste line jetted outside of building for blockage
- MNPCA limited site investigation update– soil and vapor borings LSI report in process with Environmental Troubleshooters Inc. Petrofund backups approved if needed, State has been updated
- MAU for kitchen lockout alarms - gas valve arrived to be installed
- AHU 2 air handler return motor – motor arrived on site waiting for interference fit pulley