

Transportation and Maintenance Report

Report for March 16, 2026

Transportation

1. Bus #46, clean SCR after treatment system, replace low coolant level sensor.
2. Lunch truck, wiper blades.
3. Van #2 Oil change.

Pacific High School

1. Replace drains on drinking fountains, North Hall.
2. Repair air leak in Metal Shop.

Driftwood

1. Replace kitchen triple sink faucet.
2. Repair flush valves in elementary wing girl's restroom.
3. Repair ceiling tiles in room #6 (Eagle's Nest).
4. Repair/adjust table legs in library.
5. Patch holes in roof of storage container.
6. Replace blinds on door to counselor room.
7. Work on issues with reader board.
8. Install doorbell at cafeteria door.
9. Install end cap in gutter above main hall doors to playground, excess water created a leak.