



Robert P. Stone, Owner ~ 563 E. St. Kitts Dr. ~ Meridian, ID 83642
208-888-2175 ~ 208-871-5922 cell

To: Homedale High School

Attn: Tom Muir

Bid Proposal for Track Repairs

The following prices are for the track repairs at Homedale High School.

Option 1. Crack repair only.

The rubber on each side of the crack will be cut out two inches on each side and removed. The crack will then be cleaned and filled with liquid asphalt until level with existing surface. Rubber will then be added until level with existing rubber.

Price \$8,300.00

Option 2. Crack repair and spray coat of binder.

Crack repair same as option one. Once repairs are done the track will be sprayed with two coats of latex binder. This will fill in all the voids and hold the rubber together prolonging the life of your track. Once the spray coat dry's the track will be re-painted.

Price \$35,000.00

Option 3. 1/4 inch re-top of track.

Crack repair same as option one. Once repairs are done the track will get two new layers of rubber and a final spray coat of latex binder. Track will then be re-painted.

Price \$74,000.00

With my company, you can be confident that you will be getting the highest quality of workmanship. I have twenty years of experience in this business and have worked on all types of track surfaces. I have personally installed hundreds of running tracks and have also had the privilege of painting some very profile jobs such as Hayward Field for the 2008 Olympic Trials, University of Arkansas 2004 NCAA indoor championships, Boise State University's outdoor and indoor tracks 2012 NCAA championships and Norfolk State University 2001 Junior Olympics just to name a few. You will find that I am very meticulous in my work, and I guarantee that you will not find another track company that will give you higher quality or better customer service than The TRACK DOCTOR. I look forward to doing business with you

Robert Stone/Owner
The Track Doctor