

Pricing to repair leaking 1985 Carrier 19DK chiller.

The chiller was pressurized and leaks were found that necessitate the removal of all Freon and oil, the re-gasketing of the entire chiller.

Scope of Work:

- Remove oil and refrigerant per EPA standards
- Disassemble components and replace all o-rings and gaskets and re-assemble
- Install DTE 26 oil
- Evacuate system and leak check
- Install new filters, oil, and original Freon
- Charge system to factory amount of 575# Freon
- Perform start up and log for our records

The above scope of work will be provided complete for the amount of: \$15,820.00

Freon will be billed at \$12.60 per pound and added to the proposed amount.

(Est. \$2,205.00)

Should the bearing, after inspection, the additional cost of 9,870.00 will be added.

Total P.O. amount: \$27,525.00

Entech Sales and Services

EPCNT Irving ISD Bid #07-61 37

Current Vendor for PM on Carrier chillers

Pricing to repair leaking 2005 MultiStack Chiller

The chiller was pressurized and leaks were found that necessitate the removal of all Freon and repair of the heat exchangers.

Scope of Work:

- Isolate chillers (both condenser and chilled water circuits)
- Drain Chillers
- Remove refrigerant per EPA standards
- Disassemble components and repair/replace heat exchangers and re-assemble
- Evacuate system and leak check
- Install new filters and original Freon
- Charge system to factory amount of Freon
- Backflush chillers with water to remove foreign materials
- Fill chillers with clean water
- Perform start up and log for our records

The above scope of work will be provided for the amount ranging from \$50,000 to \$75,000.

Texas Trane Sales and Service

Maintenance Bid #09-10-05 19

Current Vendor for PM on Multistack chillers