

# DIXON PUBLIC SCHOOLS #170

*"A Place to Grow"*

[www.dps170.org](http://www.dps170.org)

1335 Franklin Grove Road  
Dixon, Illinois 61021

Phone: (815) 373-4966  
Fax: (815) 284-8576

---

Margo Empen, Superintendent  
Doug Stansford, Asst. Superintendent  
Marc Campbell, Business Manager

Date: February 18, 2026  
To: Board of Education Members  
From: Margo Empen, Superintendent & Marc Campbell, CSBO  
RE: HLS Amendment – Stage Curtains at Madison and DHS

---

In accordance with Board of Education Policy 4:150 Facility Management and Building Programs a designee of the Superintendent shall facilitate compliance with the 10-year safety survey process required by the School Code. The local school board, guided by The Local Government Professional Services Selection Act Section 50 ILCS 510/0.01, is required to hire a licensed design professional to assist the district in correcting the violations using the school building code known as "Health/Life Safety Code for Public Schools," Part 180.

The HLS process requires that prior to the expenditures of the HLS fund, a licensed design professional must create a HLS amendment. The amendment is then approved by the Board of Education, submitted to the ROE for approval, and then approved by ISBE. In January 2026, the Board was informed of our need to replace the stage curtains at Madison and DHS. Replacement of the curtains is an allowable HLS expense and the next step in the process is for the Board to approve the HLS amendment.

Attached to this memorandum there are two summary exhibits.

- Exhibit A: Scheduled HLS Summary page for the Madison curtains estimated at \$42,400.
- Exhibit B: Scheduled HLS Summary page for the DHS curtains estimated at \$60,600.

Fund Balance information from SDS and Financial Summary:

- Health Life Safety Fund: Unaudited 1/31/26 \$903,000
- Architect Estimated Stage Curtain Work Cost \$103,000

Upon approval of the amendment, the next steps in the process include:

- **February 2026** – Board approval of HLS Amendment and process documentation with the ROE.
- **March 2026** – Conduct a Bid
- **March/April 2026** – Board approval of bid

It is the recommendation of District Administration that the Board approve the HLS amendment for the replacement of stage curtains as presented.

*Dixon Public Schools, in cooperation with the community, will provide students with a comprehensive educational program that produces well-educated, self-sufficient, and involved citizens.*



**Add / Edit Schedule Item**

Location(s) (Name & Room Number):*	<input type="text" value="Gymnasium Stage"/>
Priority Code:*	<input type="text" value="Required"/>
Rule Violated: *	<input type="text" value="IFC 807.2, NFPA 701"/> View () or ()
Description of the Violation:*	<input type="text" value="Stage curtains will not pass their fire retardant flame test again."/>
Recommendation to Correct Violation:*	<input type="text" value="Replace stage curtains with fire retardant material that will pass the flame test."/>
Action Id:*	<input type="text" value="Repair"/>
Specification(s):*	<input type="text" value="Replace stage curtains with fire retardant material that will pass the flame test."/>
Units Of Measure:*	<input type="text" value="LS"/>
Quantity:*	<input type="text" value="1"/>
Labor Code:*	<input type="text" value="Work will be performed by contractors"/>
Work Type:*	<input type="text" value="Safety Standards"/>
Estimated Cost: [00.00]*	<input type="text" value="\$42400.00"/>
Estimated Completion Date: [MM/DD/YYYY]*	<input type="text" value="8/1/2026"/>
Funding Type:*	<input type="text" value="Fire Prevention"/>

**ROE Adjustments**

Adjusted Amount: [00.00] \$

**ISBE Adjustments**

Adjusted Amount: [00.00] \$

Reason:

B

Add / Edit Schedule Item

Location(s) (Name & Room Number):*	Auditorium
Priority Code:*	Required
Rule Violated: *	IFC 807.2, NFPA 701 View () or ()
Description of the Violation:*	Stage curtains will not pass their fire retardant flame test again.
Recommendation to Correct Violation:*	Replace stage curtains with fire retardant material that will pass the flame test.
Action Id:*	Repair
Specification(s):*	Replace stage curtains with fire retardant material that will pass the flame test.
Units Of Measure:*	LS
Quantity:*	1
Labor Code:*	Work will be performed by contractors
Work Type:*	Safety Standards
Estimated Cost: [00.00]*	\$ 60600.00
Estimated Completion Date: [MM/DD/YYYY]*	8/1/2026
Funding Type:*	Fire Prevention

ROE Adjustments

Adjusted Amount: [00.00] \$

ISBE Adjustments

Adjusted Amount: [00.00] \$

Reason: