

FACILITIES/CONSTRUCTION REPORT

JULY 2025

BES Bleachers:

7-7 Calm, warm@78 degrees. MSEC patch holes in the locker rooms, results of anchors breaking thru CMU block when installing new bleachers, 1 worker.

7-18 Calm, warm@72 degrees. MSEC patch holes in the locker rooms, 2nd coat, results of anchors breaking thru CMU block when installing new bleachers, 1 worker.