

Northland Community Schools

Independent School District #118

School Board Report

Date: Dec24



- Annual Extinguisher Service this month with Kitchen Suppression
- Main water heater board and pressure switch failed parts on order up again
- State DLI boiler and pressure vessel inspection pass
- Some sinks have been vandalized parts on order
- MNPCA limited site investigation quotes to follow 90% reimbursement with application, this was due to new the fuel supplier spill not the school
- MAU for kitchen lockout issue being investigated
- Chiller loop leak repair later this month with no kids here