

MAINTENANCE REPORT
OCTOBER 2020

Submitted by: Reid Reagan

Maintenance staff has been installing walk thru temperature check stations with fever temperature detection at the buildings. Setting up sneeze guards at the office entrances. Replaced broken windows in the buildings to keep the rooms warm with the falling temperatures.

HIGH SCHOOL:

Replaced burnt out security lights.

BES:

Replaced faulty Differential Relief Valve in mechanical mezzanine, replaced burnt out control board to boiler #6, boiler room.

KWB:

Replaced broken safety strap on basketball hoop in gym.

VC:

Installing new LED lighting throughout the school. Restore refrigerant to the freezer in kitchen.