

**MAINTENANCE REPORT
FEBRUARY 2026**

Submitted by: Reid Reagan

Maintenance staff has been busy keeping the buildings warm and the parking lots, streets and sidewalks clear of snow/ice and sanded. Install the new AED (defibrillators) and equipment in all the buildings, at the specified locations. In addition we have assisted in the setup/cleanup of basketball games at BHS and BES.

BHS:

Replace burnt out lights in the gym. Install new TV in auto shop.

BMS:

Blackout windows/decorate the cafeteria and stage for the good attendance dance. Repair ice maker in the concessions.

BULLSHOE-VC Wing:

Solder the heating coils to the unit ventilator, heat restored. Install new TV. Install new kitchen sprayer.

BULLSHOE-KW Wing:

Replace faulty heat sensor in cooking oven.

NAPI:

Install new TV, remove and relocate another TV in classroom. Replace faulty tension spring on dishwasher door. Install new baseboards throughout the building. Install new intercoms (3) for the PA system.

BES:

Repair shot clock in gym, replace burnt out lights in gym. Install new TV in classroom. Setup for Heart Butte boys basketball games. Replace faulty heat sensor in cooking oven.

BABB:

Remove old barbed wire fence/steel posts near the playground.

BUS GARAGE:

Repair furnace, heat restored. Patch metal roof.