

MAINTENANCE REPORT NOVEMBER 2021

Submitted by: Reid Reagan

Maintenance staff has been busy securing the loose panels, trims of the buildings; cutting down and picking up the downed tree branches, limbs; and all the trash collected on the fences from the recent wind storm. Inspection of the schools roofs, contractor will be submitting report. Responded to 92 work order, all repair or service calls.

HIGH SCHOOL:

Replace faulty rubber gasket at the base of roof drain, causing leak in wall Rm 101 A wing. Replace faulty seal at the pump, dishwasher. Wired for electricity the retractable curtain at center court of gym, also wired 4 treadmills for 115 amp service in the Wellness Rm.

BES:

Restore service to kitchen, backed up grease trap caused drain to backup.

BMS:

Repair doors, part of warranty work.

NAPI:

Repaired faulty fan blower motor supplying heat to the gym. Replace faulty electrical outlet, nurses station.