

Master Facilities Plan - DRAFT



2023-2026

May 30, 2023

* Total Project Costs include A/E fee; do not include contingencies

2023-2026 Remaining Estim	ated Costs
HLS - "A" Category Required	\$0
HLS - "B" Category Required	\$1,196,866
Building Maintenance	\$4,148,132
Constal loss Books at	¢42.607.267
Capital Imp. Projects	\$12,697,267
Grand Total:	\$18,042,264

2023						
Priority Code	School	Category	ltem	Estimated Cost	Bid Costs to Date	Notes
			Subtotal	ćo		
HLS B	Todd Hall	Mechanical	Replace mechanical system piping valves with actuators	\$0 \$92,627	\$92,627	
HLS B	Todd Hall	Plumbing	Replace galvanized water piping and fixtures	\$137.494	\$137,494	
HLS B	Todd Hall	Plumbing	Replace piping and fixtures with new	\$266,304	\$266.304	
HLS B	Todd Hall	Plumbing	Provide backflow prevention devices at mop sinks	\$6,513	\$6.513	
HLS B	Rutledge Hall	Masonry	Replace chimney capstone	\$3,618	-	incorporated in cost below
			Subtotal	\$506,556		
Maintenance	Todd Hall	Masonry Tuckpointing	Miscellaneous building tuckpointing	TBD	\$86,520	
Maintenance	Rutledge Hall	Masonry Tuckpointing	Miscellaneous building tuckpointing	TBD	\$57,985	new project added
Maintenance	Lincoln Hall	Masonry Tuckpointing	Tuckpoint area above main office	TBD	\$57,985	new project added
Maintenance	Administration	Masonry Tuckpointing	Miscellaneous building tuckpointing	TBD	\$47,010	new project added
Maintenance	Todd Hall	Roofing	Replace modified bitumen roof	\$134,387	\$51,667	·
Maintenance	Rutledge Hall	Roofing	Replace TPO roof with modified bitumen	\$608,786	\$740,367	,
Maintenance	Administration	Roofing	Replace modified bitumen roof	\$200,000	\$187,567	·
Maintenance	Rutledge Hall	Mechanical	Replace exhaust fans	\$111,583	\$180,000	
Maintenance	Todd Hall	Mechanical	Replace exhaust fans	\$234,325	\$220,000	
Maintenance	Rutledge Hall	Flooring	Replace gym, multipurpose room, and library flooring	TBD	\$195,000	new project added
Maintenance	Campus	Lawn sprinkler heads	Replace lawn sprinkler heads	TBD		
			Subtotal	\$1,289,082		
Capital	Todd Hall	Plumbing	Drinking fountain replacement plus additions	TBD		new project added
Capital	Rutledge Hall	Misc	Replace window treatments - first floor	TBD	\$22,350	new project added
Capital	Todd Hall	Misc	Misc. renovations (nurse's office; toilet rooms; library)	TBD	\$317,062	new project added
Capital	Todd Hall	Classroom Furniture	Replace pre-K and K classroom furniture	\$141,777	\$65,892	
Capital	Rutledge Hall	Furniture	Replace library furniture & casework	TBD	\$168,000	
Capital	Rutledge Hall	Furniture	Classroom rocking chairs	\$11,200	\$11,200	new project added
Capital/Donation	Lincoln Hall	Equipment	Replace (4) basketball hoops	\$77,063	\$77,063	\$37,500 donation; new
						project added
			Subtotal	\$230,040		
			Total 2023 Cost		\$2,911,542	

2024						
Priority Code	School	Category	Item		Estimated Cost	Notes
				Subtotal	\$0)
HLS B	Rutledge Hall	Plumbing	Provide sprinkler flow switch		\$7,598	1
HLS B	Rutledge Hall	Plumbing	Replace galvanized water piping and fixtures		\$537,963	
HLS B	Rutledge Hall	Plumbing	Install vacuum breaker faucets		\$9,118	
				Subtotal	\$554,679)
Maintenance	Todd Hall	Asphalt	Sealcoat, stripe, crack fill parking lot		\$12,361	
Maintenance	Rutledge Hall	Mechanical	Replace classroom univents			maybe swap with Todd Hall for 2025
Maintenance	Rutledge Hall	Mechanical	Replace cabinet unit heaters		\$48,243	maybe swap with Todd Hall for 2025
Maintenance	Rutledge Hall	Mechanical	Replace fan coil units		\$66,162	maybe swap with Todd Hall for 2025
Maintenance	Todd Hall	Flooring	Replace gym flooring		\$103,853	New project added to plan
Maintenance	Lincoln Hall	Enclosure	Replace painted insulated panels at courtyard		TBC	New project added to plan
				Subtotal	\$1,402,246	
Capital	Todd Hall	Classroom Furniture	Replace 1st grade classroom furniture		\$144,730)
Capital	Rutledge Hall	Misc	Courtyard Renovation		\$767,448	}
Capital	Lincoln Hall	Misc	Plaza (Door 11) Renovations			deferred from 2023
Capital	Todd Hall	Misc	Courtyard Renovation		\$767,448	deferred from 2023
Capital	Rutledge Hall	Misc	Replace window treatments - second floor			New project added to plan
Capital	Rutledge Hall	Plumbing	Drinking fountain replacement			New project added to plan
Capital	Todd Hall	Lighting	Replace classroom lighting		\$744,327	
Capital	Rutledge Hall	Misc	Gymnasium presentation system		\$50,000	New project added to plan
Capital	TBD	Misc	Branding & Recognition		TBC	New project added to plan
				Subtotal	\$3,174,874	

Total 2024 Cost \$5,131,798

riority Code	School	Category	Item		Estimated Cost	Notes
		.curcho.y			. Lotiniated Cost	
				Subtotal	\$C)
.S B	Lincoln Hall	Masonry	Underpin and replace cracked masonry walls		\$47,870)
LS B	Lincoln Hall	General Trades	Miscellaneous exterior soffit repairs		\$39,891	
LS B	Lincoln Hall	General Trades	Repair foundation wall leaks		\$47,870)
				Subtotal	\$135,630)
aintenance	Lincoln/Rutledge	Asphalt	Sealcoat, stripe, crack fill parking lot		\$33,381	
aintenance	Todd Hall	Mechanical	Replace classroom univents		\$1,121,660	maybe swap with Rutledge Hall for 202
aintenance	Todd Hall	Mechanical	Replace cabinet unit heaters		\$50,656	maybe swap with Rutledge Hall for 202
laintenance	Todd Hall	Mechanical	Replace fan coil units		\$23,157	maybe swap with Rutledge Hall for 202
aintenance	Todd Hall	Plumbing	Replace tunnel piping		TBD)
				Subtotal	\$1,228,854	ļ
apital	Todd Hall	Classroom Furniture	Replace 2nd grade classroom furniture		\$151,967	'
pital	Todd Hall	Addition	Classroom Addition		\$3,702,615	New project added to plan
ıpital	Lincoln Hall	Misc	Courtyard Renovation		\$234,325	New project added to plan
				Subtotal	\$4,088,907	
			Total 2025 Co	st	\$5,453,392	
			Total 2025 Cc	ost	\$5,453,392	
	- Proposed			ost		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
		Category	Total 2025 Co	ost	\$5,453,392 Estimated Cost	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
		Category			Estimated Cost	Notes
		Category		Subtotal		Notes
		Category		Subtotal	Estimated Cost	Notes
riority Code	School		item		Estimated Cost \$0	Notes
		Category		Subtotal Subtotal	Estimated Cost	Notes
iority Code	School Todd Hall	Painting	iltem Paint interior	Subtotal	\$c \$c \$227,950 \$227,950 \$227,950	Notes
iority Code	Todd Hall	Painting Casework	Paint interior Replace classroom casework	Subtotal Subtotal	\$c \$c \$227,950 \$227,950 \$227,950 \$328,248	Notes
iority Code aintenance pital pital	Todd Hall Todd Hall Todd Hall	Painting Casework Lighting	Paint interior Replace classroom casework Replace corridor/office lighting to LED	Subtotal Subtotal	\$c \$c \$227,950 \$227,950 \$328,248 \$455,901	Notes
aintenance pital pital pital	Todd Hall Todd Hall Todd Hall Todd Hall Todd Hall	Painting Casework Lighting Classroom Furniture	Paint interior Replace classroom casework Replace corridor/office lighting to LED Replace shared instructional furniture	Subtotal Subtotal	\$0 \$0 \$227,950 \$227,950 \$328,248 \$455,900 \$45,590	Notes
aintenance pital pital pital pital pital pital	Todd Hall Todd Hall Todd Hall Todd Hall Todd Hall Todd Hall Rutledge Hall	Painting Casework Lighting Classroom Furniture Casework	Paint interior Replace classroom casework Replace corridor/office lighting to LED Replace shared instructional furniture Replace classroom casework	Subtotal Subtotal	\$6 \$6 \$227,956 \$227,956 \$328,248 \$45,901 \$45,590 \$683,851	Notes
aintenance pital pital pital	Todd Hall Todd Hall Todd Hall Todd Hall Todd Hall	Painting Casework Lighting Classroom Furniture	Paint interior Replace classroom casework Replace corridor/office lighting to LED Replace shared instructional furniture	Subtotal Subtotal	\$6 \$6 \$227,956 \$227,956 \$328,248 \$45,901 \$45,590 \$683,851	Notes Notes