IKE Capital Improvement Plan

1	Site Work
1.1	North Playground Lot Replacement
1.2	Wood Playground Equipment Replacement
1.3	Parking Lot A Replacement
1.4	Parking Lot B Replacement
2	Building Envelope & Roofing
2.1	Single Pane Window Replacement
2.2	Exterior Facade Painting
2.3	Roof Areas 2,3,4,5,6,7 Replacement
3	Building Interior
3.1	MPR Floor Replacement
3.2	VCT Flooring Replacement
4	Building Systems
4.1	Washroom Fixture Replacement
4.2	HVAC Retrofit
4.3	Building Clock Replacement
5	Health & Life Safety Items

5.1 10 Year LS Survey Items

KEY

WORK COMPLETED

WORK DEFERRED

Ross Capital Improvement Plan

1	Site Work
1.1	Parking Lot Replacement
2	Building Envelope & Roofing
2.1	Single Pane Window Replacement
2.2	Wood Siding Replacement
2.3	Roof Area 1 & 3 Replacement
3	Building Interior
3.1	MPR Floor Replacement
3.2	VCT Flooring Replacement
3.3	MPR Divider Replacement
4	Building Systems
4 4.1	Building Systems Washroom Fixture Replacement
-	
4.1	Washroom Fixture Replacement
4.1 4.2	Washroom Fixture Replacement Galvanized Water Piping Replacement 103-116
4.1 4.2 4.3	Washroom Fixture Replacement Galvanized Water Piping Replacement 103-116 WR 209 & 207 Fixture Replacement
4.1 4.2 4.3 4.4	Washroom Fixture Replacement Galvanized Water Piping Replacement 103-116 WR 209 & 207 Fixture Replacement WR 102A, 103A, 104A Improvements
4.1 4.2 4.3 4.4 4.5	Washroom Fixture Replacement Galvanized Water Piping Replacement 103-116 WR 209 & 207 Fixture Replacement WR 102A, 103A, 104A Improvements HVAC Retrofit Phase 1
4.1 4.2 4.3 4.4 4.5 4.6	Washroom Fixture Replacement Galvanized Water Piping Replacement 103-116 WR 209 & 207 Fixture Replacement WR 102A, 103A, 104A Improvements HVAC Retrofit Phase 1 HVAC Retrofit Phase 2

KEY

WORK COMPLETED

WORK DEFERRED

Sullivan Capital Improvement Plan

1	Site Work
1.1	Parking Lot Replacement
2	Building Envelope & Roofing
2.1	Wood Siding Replacement
2.2	Roof Area 1 Replacement
2.3	Roof Area 2,3,5,7,8 Replacement
3	Building Interior
3.1	MPR Floor Replacement
3.2	VCT Flooring Replacement
4	Building Systems
4.1	HVAC Retrofit Phase 1
4.2	HVAC Retrofit Phase 2
4.3	Building Clock Replacement
5	Health & Life Safety Items
F 1	10.1/ 10.0

5.1 10 Year LS Survey Items

KEY

WORK COMPLETED

WORK DEFERRED

MacArthur Capital Improvement Plan

1	Site Work
1.1	Parking Lot Replacement
2	Building Envelope & Roofing
2.1	Wood Siding Replacement
2.2	Roof Area 15, 16, 20 Replacement
2.3	Roof Area 8, 17 Replacement
3	Building Interior
3.1	VCT & Carpet Flooring Replacement
4	Building Systems
4.1	HVAC Retrofit Phase 1
4.2	HVAC Retrofit Phase 2
4.3	Building Clock Replacement
4.4	Galvanized Piping Replacement @ LR's
4.5	Washroom Upgrades 312, 316, 414, 410
4.6	Toilet Fixture Replacement
5	Health & Life Safety Items
5.1	10 Year LS Survey Items

WORK COMPLETED

WORK DEFERRED

Grodsky Capital Improvement Plan

1	Site Work	
1.1	Parking Lot Replacement	
1.2	PHYBS Baseball Field Rehab	
2	Building Envelope & Roofing	
2.1	Wood Siding Replacement	
2.2	Roof Area 10 Replacement	
2.3	Roof Area 11 Replacement	
3	Building Interior	
3.1	Flooring Replacement	
3.2	Structural Repairs @ Windows	
4	Building Systems	
4.1	District Wide Camera System Upgrades	
4.2	District Wide Intercom System Upgrades	
5	Health & Life Safety Items	
5.1	10 Year LS Survey Items	