

Derby High School

- Removed multiple cabinets from building.
- Installed exterior door alarms in sports wing.
- Replaced thermostat in classroom 106.
- New blinds installed in classrooms 118,117, and 116.
- Repaired thermostat in LRU.
- Replaced towel dispensers in LRU.
- Repaired door chime in LRU.
- Installed new door hardware in vice-principal's office.
- Replaced fountain filters.

DERBY MIDDLE SCHOOL

- Repaired gym closet door.
- Repaired flush valve in faculty restroom.
- Replaced ballast and motion sensor for stairwell fixture.
- Remedied heat issue in classroom C11.
- Hung multiple bulletin boards throughout hallways.

IRVING ELEMENTARY

- Repairs made to main office exterior door intercom.
- Replaced heating valves in classrooms 212,222, and 224.
- Repaired playground gate.
- Installed new domestic hot water circulator pump.
- Installed new lock core in media center and sensory room doors.
- Removed and lubricated all door lock cores on lower level.
- Set up multiple classroom tables.
- Assembled and delivered multiple computer charging stations.
- Synthetic gym floor was scrubbed,conditioned,and buffed.

BRADLEY ELEMENTARY

- Repaired 2 exterior camera domes.
- Installed new sump pump in boiler room.
- Repaired boiler room exterior door lock.
- Synthetic gym floor was scrubbed,conditioned,and buffed.
- Repaired upper hall girls restroom sink.
- Replaced water fountain filters.
- Serviced gym air handler units.
- Assembled and delivered multiple computer charging stations.

Survey Solutions

- Introduction of handheld and backpack electrostatic sprayers in all 4 schools.
- Increased custodial coverage at DHS.
- Part-time floater position hired and assigned to Irving.
- Reviewed cleaning practices and assignments with staff.
- Additional grant funded sanitation attendant being hired for LRU.

