

Transportation and Maintenance Report

January Meeting 2025

Driftwood School

1. Heating system repairs main hall, rooms 5, 6 and 9.
2. Repairs to merry-go-round.

Pacific High School

1. Cut up tree; fell during winter storm over the break.
2. Clean up in courtyard area.
3. Replace faucet in athletic room.
4. Pressure wash porch roof front of building.
5. Replace well pump control.
6. Replace bad siding on lower south side of bus garage, and front of district office.
7. Reseal repair leaks upper west wall of gymnasium.

Transportation

1. Bus #52, add DEF and washer fluid.
2. Bus #50, adjust head lamps.
3. Bus #44, replace midship carrier bearing.
4. Order turbo charger for bus #46.
5. Bus #56, clean EGR tubes.

Waste Water

1. All daily and monthly monitoring.