1. COUNTY CODE 2. DISTRICT CODE/NAME 1910, Midwest Central CUSD 191								3. FACILITY CODE/NAME MIDWEST CENTRAL MIDDLE SCHOOL							
	Location(s) (Room No)	Rule Violated	Description of the violation	Recommendation to correct violation	Action I.D.	Priority Code	Specification(s)	- 11-	Jnits Of Measure	Quantity	Labor Code		ISBE Adjustment	Estimated Completion Date	Funding Type
1	Dispenser,	NFPA 70-210	Non GFI type outlet adjacent to water source.	Replace receptacle with GFI type.	f	b.	Replace receptack with GFI type.	eE	≣a.	2	2	\$400.00		8/15/2036	F
2	Cafeteria restroom H2	ISPC 890 . 610	The urinal is broken.	See Specification.	f	b.	Replace urinal and provide new water supply		Ea.	1	2	\$2,000.00		8/15/2030	0
3	Vestibule C101	105 ILCS 128/5	limited to a	Improve building security and access control by removing the interior vestibule glazing and openings to create a secure visitor entrance vestibule by subdividing C101 into a secure visitor entrance with secure access to the school office.	е	C.	Improve building security and access control by removing the interior vestibule glazing and openings to create a secure visitor entrance vestibule by sub-dividing C101 into a secure visitor entrance with secure access to the school office	e s	Ξa.	1	2	\$115,000.00		8/15/2031	F
 Violation	n / Work Item Listin	ng		office.			to the school office	•							