

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD
Job #JN4654 - Desoto High School Elevator
600 Eagle Dr
Desoto, TX 75115

Estimate #	5243
Date	7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected:</p> <p>Unit 1</p> <p>Rule: A17.1 8.6.4.15</p> <p>Code Year: 2016</p> <p>Violation: Provide Operational Two-Way Communications</p> <p>Responsibility: See below proposal</p> <p>Rule: A17.1 8.6.4.7.1</p> <p>Code Year: 2007</p> <p>Violation: Provide Operational Emergency Light and Alarm Bell</p> <p>Responsibility: See below proposal</p> <p>SCOPE OF WORK:</p> <p>-Provide and Install new ADA Handsfree Emergency Phone on Unit 1.</p> <p>-Provide and Install new emergency light battery on Unit 1.</p>	1.00	\$3,500.00	\$3,500.00

Item	Description	Qty	Price	Amount
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected:</p> <p>Unit 2</p> <p>Rule: A17.1 8.6.4.15</p> <p>Code Year: 2016</p> <p>Violation: Provide Operational Emergency Light and Alarm Bell</p> <p>Responsibility: See below proposal</p> <p>Rule: A17.1 8.6.4.16</p> <p>Code Year: 2016</p> <p>Violation: Provide Operational Two-Way Communications</p> <p>Responsibility: See below proposal</p> <p>Rule: A17.1 8.6.5.5.2</p> <p>Code Year: 2007</p> <p>Violation: Install an oil collection container in the pit with a capacity of not more than 5 gallons.</p> <p>Responsibility: See below proposal</p> <p>Rule: A17.1 8.6.4.8.1</p> <p>Code Year: 2007</p> <p>Violation: Provide removal of trash from machine room floor.</p> <p>Responsibility: Building Owner.</p> <p>Rule: A17.1 2.8.1</p> <p>Code Year: 2007</p> <p>Violation: Replace damaged traveling cable</p> <p>Responsibility: See below proposal.</p> <p>SCOPE OF WORK:</p> <p>-Provide and Install new ADA Handsfree Emergency Phone on Unit 2.</p> <p>-Provide and Install new emergency light battery on Unit 2.</p> <p>-Provide new oil collection container in elevator pit.</p> <p>-Provide and install new Travel Cable on Unit 2.</p>	1.00	\$16,500.00	\$16,500.00
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected:</p> <p>Unit 3</p> <p>Rule: A17.1 8.6.4.15</p> <p>Code Year: 2016</p> <p>Violation: Provide Operational Two-Way Communications</p> <p>Responsibility: See below proposal</p> <p>Rule: A17.1 8.6.4.7.1</p> <p>Code Year: 2007</p> <p>Violation: Provide Cleaning of Pit</p> <p>Responsibility: See below proposal</p> <p>SCOPE OF WORK:</p> <p>Provide and Install new ADA Handsfree Emergency Phone on Unit 3.</p> <p>Clean elevator pit on Unit 3.</p>	1.00	\$4,500.00	\$4,500.00
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected:</p> <p>Unit 4</p> <p>Rule: A17.1 2.8.1</p> <p>Code Year: 2007</p> <p>Violation: Replace damaged traveling cable</p> <p>Responsibility: See below proposal.</p> <p>Rule: A17.1 8.6.4.8.1</p> <p>Code Year: 2007</p> <p>Violation: Provide removal of water from machine room floor</p> <p>Responsibility: Building Owner</p>	1.00	\$15,400.00	\$15,400.00

Sub Total

\$39,900.00

Total

\$39,900.00

SPECIAL INSTRUCTIONS/EXCLUSIONS

This price is valid for 30 days from the date of this proposal.

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD
Job #JN4674 - JN 4473 DISD West Middle School Elevator Repairs
800 N Westmoreland Rd
Desoto, TX 75115

Estimate # 5245
Date 7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	Based on your recent elevator inspection, the following deficiencies to be corrected. Unit 1 Rule: A17.1 8.6.5.5.1 Code Year: 2007 Violation: Provide replacement of hydraulic flex hose, no install date or replacement date indicated on the hose. (6 yrs) Responsibility: See below proposal SCOPE OF WORK: • Provide and Install new hydraulic flex hose and tag on one elevator.	1.00	\$3,000.00	\$3,000.00

Sub Total \$3,000.00
Total \$3,000.00

SPECIAL INSTRUCTIONS / EXCLUSIONS

This price is valid for 30 days from the date of this proposal.

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD
Job #JN4511 - DISD East Middle School Elevator Repairs
601 E Belt Line Rd
Desoto, TX 75115

Estimate # 5247
Date 7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected.</p> <p>Unit 1</p> <p>Rule: A17.1 8.6.4.15</p> <p>Code Year: 2016</p> <p>Violation: Provide Operational Two-Way Communications</p> <p>Responsibility: See below proposal</p> <p>SCOPE OF WORK:</p> <ul style="list-style-type: none"> • Provide and Install new ADA Handsfree Emergency Phone 	1.00	\$3,000.00	\$3,000.00
Sub Total				\$3,000.00
Total				\$3,000.00

SPECIAL INSTRUCTIONS / EXCLUSIONS

This price is valid for 30 days from the date of this proposal.

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD
Job #JN4474 - DISD Katherine Johnson Tech Magnet Academy
1200 Academy Way
Desoto, TX 75115

Estimate # 5244
Date 7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	Based on your recent elevator inspection, the following deficiencies to be corrected. Unit 1 Rule: A17.1 8.6.4.15 Code Year: 2016 Violation: Provide Operational Two-Way Communications Responsibility: See below proposal Rule: A17.1 8.6.4.15 Code Year: 2016 Violation: Provide Operational Emergency Light and Alarm Bell Responsibility: See below proposal SCOPE OF WORK: • Provide and Install new ADA Handsfree Emergency Phone. • Provide and Install new emergency light battery.	1.00	\$3,000.00	\$3,000.00
Sub Total				\$3,000.00
Total				\$3,000.00

SPECIAL INSTRUCTIONS/EXCLUSIONS

This price is valid for 30 days from the date of this proposal.

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD

Job #JN4675 - DISD McCowan Middle School Elevator Repairs
1500 Majestic Meadow Dr
Glenn Heights, TX 75154

Estimate # 5246
Date 7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected.</p> <p>Unit 1 Rule: A17.1 8.6.4.15 Code Year: 2016 Violation: Provide Operational Two-Way Communications Responsibility: See below proposal</p> <p>Unit 1 Rule: A17.1 8.6.4.7.1 Code Year: 2017 Violation: Provide cleaning of pit Responsibility: See below proposal</p> <p>SCOPE OF WORK: • Provide and Install new ADA Handsfree Emergency Phone. • Clean Elevator Pit.</p>	1.00	\$6,100.00	\$6,100.00

Sub Total \$6,100.00
Total \$6,100.00

SPECIAL INSTRUCTIONS/EXCLUSIONS

This price is valid for 30 days from the date of this proposal

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____

ESTIMATE

Green Roofing & Construction
4125 Sicily Dr
Frisco, TX 75034
(817) 562-3332

Sales Representative
Brian Robertson
(214) 282-1544
Brianr@greenrooftx.com



Desoto ISD
Job #JN4676 - Desoto ISD Freshman Center Elevator Repairs
620 S Westmoreland Rd
Desoto, TX 75115

Estimate # 5248
Date 7/29/2025

Item	Description	Qty	Price	Amount
Elevator Repair	<p>Based on your recent elevator inspection, the following deficiencies to be corrected.</p> <p>Unit 1 Rule: A17.1 2.37.3.1.8 Code Year: 2016 Violation: Fireman Service Phase I Car Visual Signal Not Working Responsibility: See below proposal</p> <p>Unit 1 Rule: A17.1 8.6.4.7.1 Code Year: 2007 Violation: Provide cleaning of pit Responsibility: See below proposal</p> <p>Unit 1 Rule: A17.1 8.6.4.7.4 Code Year: 2007 Violation: Provide a pit stop switch accessible from access entrance. Secure piping. Responsibility: See below proposal</p> <p>SCOPE OF WORK:</p> <ul style="list-style-type: none"> • Troubleshoot Fire Service Phase I for repair. • Clean Elevator Pit. • Secure loose pit stop switch and mount for safe and proper operation. 	1.00	\$7,500.00	\$7,500.00
Sub Total				\$7,500.00
Total				\$7,500.00

SPECIAL INSTRUCTIONS / EXCLUSIONS

This price is valid for 30 days from the date of this proposal

Upon approval, please sign and return:

Sign: _____

Print: _____

Title: _____

Date: _____