

## FACILITIES/CONSTRUCTION REPORT

### AUGUST 2026

#### BMS FOOTBALL FIELD:

8-28 Calm, warm@76 degrees. Kinto Contractors repair chain link fence, rewire to posts and top rail, 4 workers.

8-29 Rain, warm@70 degrees. Kinto Contractors locate sprinkler heads mark with flag, haul in topsoil, pick/remove rocks, 1 skidsteer, 1 dump truck, 4 workers.