

A black and white photograph of a hand pointing with a pen at a technical drawing, likely a floor plan or architectural blueprint. The drawing contains various lines, dimensions, and labels such as 'MEN WASHROOM', 'WOMEN WASHROOM', 'HOUSE KEEPING', 'PHOTO COPIER', and '202'. Dimensions like '8'-3 23/64"', '6'-1 7/16"', and '10 5/64"' are visible. The image is framed by black curved corners.

Maintenance and Operations



Overview

- ❖ **Campus Security Upgrades**
- ❖ **State & City Inspections**
- ❖ **HVAC Repair & Replacement**
- ❖ **Portable Building Installation**
- ❖ **Paint Schedule**



A black and white photograph of a hand pointing at a technical drawing of a house layout. The drawing includes various rooms such as 'WOMEN WASHROOM', 'MEN WASHROOM', 'HOUSE KEEPING', and 'PHOTO COPIER'. Dimensions are given in feet and inches, such as '8'-3 23/64"', '6'-1 7/16"', and '10 5/64"'. The drawing also features various symbols, including circles, diamonds, and lines, representing architectural details. The hand is pointing at a specific area of the drawing, likely indicating a point of interest or a specific feature.

Safety and Security



Safety and Security

- ❑ Fire Systems: Sprinkler, Fire Extinguisher, Fire Alarm Panel, Ansul.
- ❑ Chiller/Boiler: Annual cleaning, repairs and state requirements.
- ❑ Cooling Tower: Bi-Annual cleaning.
- ❑ Chill Water Systems: Monthly chemical treatments.
- ❑ Gas Test: Annual gas test for Railroad Commission of Texas.
- ❑ Safety: New Fencing and Security Window Film
- ❑ City Water: Backflow Testing for City of Huntsville.
- ❑ Elevator: Inspection, Licensing and Elevator Modifications.
- ❑ Medical Waste: Disposal handled by licensed contractor.
- ❑ IPM: Maintained per EPA standards



Safety and Security (Continued)

- ❑ Door access at every campus.
- ❑ CrisisGo- Emergency Alert System. On all district PC's and most all district staff phones.
- ❑ DSC- New cellular based monitored security system.

A black and white photograph of an architectural floor plan. A hand is visible in the upper left, holding a pen and pointing to a specific area on the drawing. The drawing includes various rooms and dimensions. Labels include 'MEN WASHROOM', 'WOMEN WASHROOM', 'HOUSE KEEPING', 'PHOTO COPIER', and 'WASHROOM'. Dimensions like '8'-3 23/64"', '[2524]', '3'-1 13/64"', and '[768]' are visible. There are also some numbers in circles, like '18' and '15'. The image has a high-contrast, slightly grainy appearance.

Huntsville High School



HHS Completed Projects

- ☐ Security film for outside windows.
- ☐ Repaired kitchen exhaust and ansul system.
- ☐ Removed several trees around the campus.
- ☐ Installed new cellular based security system.
- ☐ Repaired bridge on Hornet Way from Transportation.
- ☐ Painted 1800 & 1900 hallways, red & blue serving lines in kitchen, offices 1302, 1910, 1015 & the restrooms.
- ☐ Installed new gas line to the kitchen Ansul system.
- ☐ Replaced water heater in the band hall.
- ☐ Replaced boiler in the band hall.
- ☐ Replaced boiler exhaust vents in Plant 1.
- ☐ Installed new chair lift in the Paul Bohan gym.
- ☐ Cleaned windows and pressure washed the building.
- ☐ Replaced carpet with VCT in several rooms.
- ☐ Replaced water heater in the kitchen.



A black and white photograph of an architectural blueprint for Mance Park Middle School. A hand is visible in the upper left, holding a pen and pointing to a specific detail on the drawing. The drawing includes various room labels such as 'MEN WASHROOM', 'WOMEN WASHROOM', '202 HOUSE KEEPING', 'PHOTO COPIER', and 'COFFEE BAR'. It also features numerous dimension lines with measurements like '8'-3 23/64"', '10 5/64"', and '6'-1 7/16"'. The drawing is framed by a black border with rounded corners.

Mance Park Middle School



MPMS Completed Projects

- ❑ Security film for outside windows.
- ❑ Installed new heat pump a/c units throughout the building.
- ❑ Removed trees in several locations on campus.
- ❑ Repaired several roof leaks on the second floor.
- ❑ Installed new canopy & lighting for the car student pick up area in the back of the building.
- ❑ Cleaned the windows on the building.
- ❑ Installed 140 feet of concrete curb behind the old kitchen parking lot.
- ❑ Installed bottle filler cooler in the kitchen.
- ❑ Installed new hose bibb on the football field.
- ❑ Installed a new cellular based security system.
- ❑ Installed new walk-in refrigeration controls.



A black and white photograph of a hand pointing at architectural blueprints. The hand is holding a pen and pointing at a specific area on the blueprint. The blueprint contains various technical drawings, including floor plans, dimensions, and labels such as "MEN WASHROOM", "202 HOUSE KEEPING", "WOMEN WASHROOM", and "PHOTO COPIER". The name "Scott Johnson" is overlaid in large, bold, black text across the center of the image. At the bottom center, there are three small circles: a yellow one on the left, a black one in the middle, and a yellow one on the right.

Scott Johnson



Scott Johnson Completed Projects

- ❑ Painted several classrooms.
- ❑ Installed several new heat pump a/c systems throughout the bldg.
- ❑ Repaired water leak in the wall at the Louis Davis Gym.
- ❑ Installed portable buildings with canopy and deck.
- ❑ Removed trees near building & trimmed several trees.
- ❑ Repaired water supply lines and sewer connections.
- ❑ Installed border timbers around existing playground.
- ❑ Installed a new cellular based security system.
- ❑ Pressure washed the building & cleaned windows.



A black and white photograph of an architectural floor plan for a school. A hand is visible in the upper left, holding a pen and pointing at a specific room. The plan includes various rooms such as a 'WOMEN WASHROOM', 'MEN WASHROOM', 'HOUSE KEEPING', and 'PHOTO COPIER'. Dimensions and room numbers are scattered throughout the drawing. The image is framed by black curved corners.

Huntsville Elementary School



HES Completed Projects

- ❑ Painted 2nd grade classrooms.
- ❑ Installed several a/c heat pump systems.
- ❑ Power washed the front of the building.
- ❑ Installed new cellular based security system.
- ❑ Installed new walk-in refrigeration controls.
- ❑ Cleaned the windows on the building.
- ❑ Constructed wider bus ramp with concrete curbs.



A black and white photograph of an architectural blueprint for Samuel Walker Houston Elementary School. A hand is visible in the upper left, holding a pen and pointing to a specific detail on the drawing. The drawing includes various room labels such as 'WOMEN WASHROOM', 'MEN WASHROOM', 'HOUSE KEEPING', and 'PHOTO COPIER'. Dimensions and room numbers are also present, such as '[2524]', '[2521]', '[2522]', '[2523]', '[2524]', '[2525]', '[2526]', '[2527]', '[2528]', '[2529]', '[2530]', '[2531]', '[2532]', '[2533]', '[2534]', '[2535]', '[2536]', '[2537]', '[2538]', '[2539]', '[2540]', '[2541]', '[2542]', '[2543]', '[2544]', '[2545]', '[2546]', '[2547]', '[2548]', '[2549]', '[2550]', '[2551]', '[2552]', '[2553]', '[2554]', '[2555]', '[2556]', '[2557]', '[2558]', '[2559]', '[2560]', '[2561]', '[2562]', '[2563]', '[2564]', '[2565]', '[2566]', '[2567]', '[2568]', '[2569]', '[2570]', '[2571]', '[2572]', '[2573]', '[2574]', '[2575]', '[2576]', '[2577]', '[2578]', '[2579]', '[2580]', '[2581]', '[2582]', '[2583]', '[2584]', '[2585]', '[2586]', '[2587]', '[2588]', '[2589]', '[2590]', '[2591]', '[2592]', '[2593]', '[2594]', '[2595]', '[2596]', '[2597]', '[2598]', '[2599]', '[2600]'.

Samuel Walker Houston Elementary School



Samuel Walker Houston Completed Projects

- ❑ Power washed the front of the bldg.
- ❑ Painted hallways, and 2nd grade classrooms.
- ❑ Removed tree limbs and trees.
- ❑ Installed new cellular based security system.
- ❑ Installed new fire system in the walk-in freezer.
- ❑ Installed a concrete wall & French drain system in the back area of the school.
- ❑ Cleaned the windows on the building.
- ❑ Installed portable building canopy & deck.



An architectural floor plan of a school building. A hand is pointing with a pen to a room labeled '15'. Other rooms include '17 MEN WASHROOM', '202 HOUSE KEEPING', '18 WOMEN WASHROOM', and '16 PHOTO COPIER'. Dimensions like '8'-3 23/64\"/>

Scott Johnson Elementary School



SLC Completed Projects

- ❑ Installed new metal frames and doors.
- ❑ Installed new receptacle for projector.
- ❑ Moved several switches in the building for projector layout.
- ❑ Painted outer wall in old stage area.
- ❑ Installed new chill water pipe insulation.
- ❑ Replaced ceiling tiles in the building.
- ❑ Moved furniture in several offices.



A black and white photograph of an architectural floor plan for a school. A hand is visible in the upper left, holding a pen and pointing at a specific room. The floor plan includes various rooms such as 'WOMEN WASHROOM', 'MEN WASHROOM', 'HOUSE KEEPING', and 'PHOTO COPIER'. Dimensions and room numbers are scattered throughout the drawing. The image has a high-contrast, slightly grainy aesthetic.

Estella Stewart Elementary School



E. Stewart Completed Projects

- ❑ Moved and reassembled playground.
- ❑ Power washed the front of the bldg.
- ❑ Repaired MAU system for the kitchen.
- ❑ Painted 2nd grade classrooms, front entrance foyer & outdoor gym restrooms.
- ❑ Installed new storm drainage system.
- ❑ Installed portable buildings, canopy & deck.
- ❑ Installed new fire system in the walk-in freezer.
- ❑ Installed new cellular based security system.
- ❑ Repainted the parking lot striping.



Miscellaneous

- ❑ Energy Management: The maintenance department is continually upgrading old lighting and HVAC equipment to a more energy efficient alternative. Huntsville ISD had several incentive projects in the 2024-2025 budget year. The total incentive funds received from Entergy was \$13,866.15.
- ❑ Maintenance personnel completed 6,066 work orders in 2024-2025.
- ❑ Main project expenditure for the summer of 2025: \$531,750.