

LMEB Service Confirmation

from Equipment Breakdown

APRA/Craig High School
Daniel Nelson
100 Panther Way
Craig, Alaska, 99921
maintenance@craigschools.com

Daniel Nelson:

Service Summary

Liberty Mutual performed the activities below on October 22, 2025 for your facility located at the above address.

- Jurisdiction Inspection. A report has been issued to the jurisdiction.

Recommendation Status

CODE violations apply to conditions or deficiencies that are defined in the laws, rules, and regulations of the jurisdiction having authority for the inspection of boilers and pressure vessels.

If Open: Please contact me via e-mail or phone to follow up on the violation within 30 days of receiving this inspection report.

If Closed: A report has been issued to the jurisdiction to allow the issuance of the certificate of operation.

Open Recommendations

Recommendation: 2025-10-01		B - Boiler not Operating for External Inspection	
Type:	Code	Status:	Open
040524AK - The boiler is not running at the time of the inspection. An external inspection is required to test the supporting safeties. If the boiler is shut down, these safeties cannot be adequately tested. Contact the inspector when the boiler is brought back into operation so an external inspection can be completed and violation cleared.			
Update:			

Recommendation: 2025-10-02		B - Safety Valve Must be Mounted on the Boiler	
Type:	Code	Status:	Open
040524AK - The safety valve on the boiler is not mounted directly to the boiler. The safety valve must be mounted as close to the boiler as possible. If it is not installed in the correct position, the safety valve may not operate as intended. Correct the installation of the safety valve so that it is mounted in an upright position and as close to the boiler as possible. This installation shall meet all current codes. Code: NBIC Part 4, 2.2.10 b)			

This report is intended to assist you in reducing the possibility of loss to equipment by bringing to your attention hazards which require prompt consideration to prevent such loss. It is based on information supplied by you and observations of conditions and practices at the time of inspection and is not intended to imply that all other hazards and conditions are under control. No liability is assumed by reason of this report as it is only advisory in nature and the final decisions must be made by you.

This report does not amend, alter, or otherwise affect, the provisions or coverage of any insurance policy. This report does not represent the status of coverage for any particular claim or loss under any such policy.



Update:

Closing Comments

Liberty Mutual appreciates your assistance in performing the activities listed above. If you have any questions or require any clarification, please let us know.

To schedule an inspection please contact the Liberty Mutual **Inspection Hotline at 877-526-0020** or email to LMEBInspections@Libertymutual.com

Sincerely,

Russell Bartlett

253-719-1107

Russell.Bartlett@LibertyMutual.com

This report is intended to assist you in reducing the possibility of loss to equipment by bringing to your attention hazards which require prompt consideration to prevent such loss. It is based on information supplied by you and observations of conditions and practices at the time of inspection and is not intended to imply that all other hazards and conditions are under control. No liability is assumed by reason of this report as it is only advisory in nature and the final decisions must be made by you.

This report does not amend, alter, or otherwise affect, the provisions or coverage of any insurance policy. This report does not represent the status of coverage for any particular claim or loss under any such policy.