NORTHSTAR BUILDERS GROUP

Celina ISD

GMP SUMMARY

Celina ES #4 - Package 2 Celina, TX

Documents Dated 10/12/2021 Estimate Dated 11/4/2021

General Conditions			1,408,923	
Allowances			1,032,107	
Owner's Contingency				
Betterment Allowance				
Supply Chain Interruption				
Pier Overages				
Energy Code Inspections				
Material Testing				
Commissioning Allowance				
Emergency Responder Amp				
City Review				
TX Dot (Turn Lane)				
Reimbursables General Requirements			1,241,297	
Pre-Construction Services				
Layout Controls				
As-Built Drawings				
Final Clean				
Daily Clean-Up				
Dumpsters				
Temporary Power Utilties				
Temporary Toilets				
Safety Supplies				
Job Signs				
Aerial/Progress Photos				
Watchman				
Temporary Fencing				
Temp Roads & Parking/Barricades				
Miscellaneous Tools & Equipment				
Shed/Tool Room				
Fire Extinguishers			4 504 000	
Sitework			1,501,903	
Concrete			4,125,988	
Masonry			1,827,588	
Metals			734,174	
Woods & Plastics			108,961	
Thermal & Roofing			2,006,495	
Doors/Windows			1,325,511	
Finishes			4,477,465	
Specialties			916,203	
Equipment			712,789	
Furnishings			572,382	
Special Contruction			78,988	
Elevator			71,510	
Fire Protection			270,910	
Mechanical & Plumbing			3,885,778	
Electrical			2,260,140	
Communications Systems			678,775	
Electronic Safety & Security Systems			306,528	
Exterior Improvements			641,458	
TO	OTAL BUILDING	COST	\$30,185,873	
Structural Steel Package GMP			3,304,721	