



Description

Transportation Building Door Frame Installation

Taken Date

11/28/2022 at 09:06 am

Uploaded By

Jason Johnson

Upload Date

11/28/2022 at 09:06 am

File Name

F25F4B0B-C9FF-419A-90A7-01AC...



Description

DSC - 2nd Floor Drywall Installation

Taken Date

11/23/2022 at 09:17 am

Uploaded By

Jack Carlson

Upload Date

11/23/2022 at 09:17 am

File Name

CFD71145-2225-45FF-BC63-7AC5...



Description

DSC - Exterior Sheathing Installation

Taken Date

11/28/2022 at 09:05 am

Uploaded By


Jason Johnson

Upload Date

11/28/2022 at 09:05 am

File Name

DCFD946-93F7-4B3B-923C-F26...



Description

Central HS Demolition - East Side

Taken Date

11/21/2022 at 10:01 am

Uploaded By

Donny Hines

Upload Date

11/23/2022 at 09:13 am

File Name

20221121_100101.jpg



Description

Central HS Demolition - Southeast Side

Taken Date

11/21/2022 at 09:58 am

Uploaded By

Donny Hines

Upload Date

11/23/2022 at 09:14 am

File Name

[20221121_095857.jpg](#)



Description

Bus Garage Siding Installation

Taken Date

11/18/2022 at 01:07 pm

Uploaded By


Nathan Norton

Upload Date

11/18/2022 at 01:08 pm

File Name

[70F9AB2E-9955-4020-86CB-46E0...](#)



Description

DSC - 1st Floor Framing Installation

Taken Date

11/18/2022 at 02:07 pm

Uploaded By

Nathan Norton

Upload Date

11/18/2022 at 02:08 pm

File Name

[5CB3E1DB-2D9F-403D-BFDD-BC1...](#)



Description

Storm Water Installation East of DSC

Taken Date

11/17/2022 at 02:24 pm

Uploaded By

Austin May

Upload Date

11/17/2022 at 02:28 pm

File Name

[0F1DB18B-0737-400D-A414-141...](#)