

Transportation Report May 2015

1. 2000 Chevy Van - oil Change Filter and Lube
and Repaired Diver side door handle
2. Bus #33 - oil change and filter and lube
3. Bus #35 - replaced AC Belt
4. Bus #36 - replaced Water pump belt
5. Bus #34 – replaced trouble and had the DEF filter sent of for cleaning
6. John Deere Z Mower – replaced gas filter and put new Belt
7. John Deere Z Track Mower – put new belt and lube
8. John Deere Front End Loader – oil change and filter and lube

All bus gets washed inside and out every week. Depending on how dirty they are.
All bus gets PM (Preventive Maintenance) check every week.
All vehicle gets PM (Preventive Maintenance) check each time they go out.
All vehicle gets wash and detail every time they go out.

Grounds and fields

We have got a good break form the rain and know trying to keep up with the mowing and trimming in and around the District. We are going to started to trim all trees in the District. We are going to started to treating all building and fence line.

Jeffrey Luna