



# MINOOKA COMMUNITY HIGH SCHOOL DISTRICT #111

*Mission: To inspire and motivate our students with an educational experience that leads to achievement and success.*

---

**DAVID BARRETT**  
*Transportation Director*

The Transportation Department has five 111 buses and one minivan that I would recommend to be disposed of. They have been out of service for a long time and have been sitting outside in the elements with windows, top hatches, and doors open. The interior alone would be a five digit figure to replace. These are owned, not leased. Please see some details below of what we know needs attention.

**Bus # 68 BlueBird**

- Entire dash cluster doesn't function
- All seats would need to be replaced
- Floor repaired
- Back Lights replaced
- All rims blasted and powder coated
- Oil pan leaks
- New shocks
- Transmission flushed/filled
- Coolant system flushed/filled
- Manifold leaks
- Gearbox leaks
- Brakes replaced
- Injectors cleaned/replaced
- Fuel tank replaced
- Batteries replaced

**Bus # 69 BlueBird**

- Backlights replaced
- Headlights replaced
- All rims blasted and powder coated
- Passenger side of cab needs to be repainted
- Oil pan leaks
- New shocks
- Transmission flushed/filled
- Coolant system flushed/filled
- Manifold leaks
- Gearbox leaks
- Brakes replaced
- Injectors cleaned/replaced
- Fuel tank replaced
- Batteries replaced
- Motor has many oil leaks that would all have to be resolved



# MINOOKA COMMUNITY HIGH SCHOOL DISTRICT #111

*Mission: To inspire and motivate our students with an educational experience that leads to achievement and success.*

---

**DAVID BARRETT**  
*Transportation Director*

## Bus # 70 International

- Replace front bumper
- Entire rearend repainted
- Entire front end repainted
- Drivers seat replaced
- Floor repaired
- All rims blasted and powder coated
- Oil pan leaks
- New shocks
- Transmission flushed/filled
- Coolant system flushed/filled
- Gearbox leaks
- Brakes replaced
- Injectors cleaned/replaced
- Fuel tank replaced
- Batteries replaced

## Bus # 74 International

- Entire rearend repainted
- Rear bumper replaced
- Repaint drivers side of bus
- Boarding stairs cut out and replaced
- All rims blasted and powder coated
- Oil pan leaks
- New shocks
- Transmission flushed/filled
- Coolant system flushed/filled
- Brakes replaced
- Injectors cleaned/replaced
- Fuel tank replaced
- Batteries replaced
- Motor doesn't turn over



# MINOOKA COMMUNITY HIGH SCHOOL DISTRICT #111

*Mission: To inspire and motivate our students with an educational experience that leads to achievement and success.*

---

**DAVID BARRETT**  
*Transportation Director*

## Bus # 75 International

- Replace drivers seat
- Floor rusted out
- All rims blasted and powder coated
- Oil pan leaks
- New shocks
- Transmission flushed/filled
- Coolant system flushed/filled
- Gearbox leaks
- Brakes replaced
- Injectors cleaned/replaced
- Fuel tank replaced
- Batteries replaced

## MiniVan # 21 Ford Freestar

- PS replace rear wheel
- PS door rusted out at bottom edge
- Hood rusted at front edge
- DS rear door rusted
- DS rear qtr panel rusted
- Interior carpet replaced
- All seats replaced

This list only represents what we know about and what we can see. There will undoubtedly be more repairs/costs as we get into it. We could either donate these to local fire departments for training purposes or have them sent to scrap yards.